

4 Days

Lumpsum Repair

After repair photos

Eric Qiang 82880282

Eric Qiang @ lkk auto.com 18/4/22

Leong Seng Motor Pte Ltd

Blk 1006 Bukit Merah Lane 2

#01-08 Singapore 159762

Tel: 62737469 Fax: 62727669

Veh No : FBP3420T

Model : UH200A

S/N	Parts Description	QTY	List Price	Nett Price	Remark
1	Rear fender / <i>cc</i>		\$ 285.00		
2	Rear no plate lamp / <i>SPS</i>		\$ 86.00		
3	Rear brake lamp assy / <i>SPS</i>		\$ 490.00		
4	Brake lamp lower / <i>MS</i>		\$ 268.00		
5	Tail cover / <i>CCP</i>		\$ 220.00		
6	Side cowling / <i>CCP</i>	2	\$ 850.00		
7	Exhaust pipe / <i>DP</i> - After repair photo's		\$ 680.00		
8	Exhaust end cap / <i>CCP</i>		\$ 176.00		
9	Rear shock absorber / <i>?</i>		\$ 310.00		
10	Air box / <i>PR</i>		\$ 280.00		
11	Clutch cover / <i>CCP</i>		\$ 350.00		
12	Rear wheel rim / <i>?</i>		\$ 390.00		
13	Rear foot board (L) / <i>CCP</i>		\$ 190.00		
14	Lower panel (L) / <i>CCP</i>		\$ 280.00		
15	Bottom cover / <i>CCP</i>		\$ 295.00		
16	Main stand assy / <i>BT</i>		\$ 340.00		
17	Front cowling / <i>CCP</i>		\$ 520.00		
18	Top cover / <i>CCP</i>		\$ 295.00		
19	Lower cover / <i>CCP</i>		\$ 285.00		
20	Front signal lamp / <i>?</i>		\$ 95.00		
21	Headlamp assy / <i>CCP</i>		\$ 460.00		
22	Front windshield / <i>CCP</i>		\$ 370.00		
23	Meter front cover / <i>CCP</i>		\$ 193.00		
24	Front compartment / <i>CCP</i>		\$ 495.00		
25	compartment door / <i>CCP</i>		\$ 190.00		
26	Maintenance cover / <i>CCP</i>		\$ 85.00		
27	Front fender / <i>CCP</i>		\$ 230.00		
28	Handle bar / <i>BT</i>		\$ 240.00		
29	Handle balancer / <i>CCP</i>		\$ 55.00		
30	Rear brake lever / <i>CCP</i>		\$ 65.00		
31	Mirror / <i>CCP</i>		\$ 98.00		
32	Front & rear no plate / <i>CCP</i>			\$ 50.00	
33	Rear box / <i>CCP</i>			\$ 200.00	
34	Rear tyre / <i>?</i>			\$ 150.00	
35	ERP IU / <i>CCP</i>			\$ 165.00	
36	Side stand extender / <i>CCP</i>			\$ 75.00	
37	Repair alignment / <i>CCP</i>			\$ 380.00	
38	Towing 2 way / <i>CCP</i>			\$ 100.00	
39	Labour / <i>CCP</i>			\$ 500.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental claims must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date:

\$ 9,166.00 \$ 1,620.00

\$ 916.60

\$ 8,249.40

Less 10%

600