

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6, #02-15@ Kaki Bukit, Singapore 417883

TEL: 6747 6106 (6 lines) Fax: 6744 2368 Email: service@smemotor.com.sg

GST:201119451E RCB NO 201119451E

Not Authorized
all
Tug M/S.

Excess?
take photo before painting
6 days.
13/4/22

M/S : Allianz Insurance Singapore Pte Ltd
79 Robinson Road #09-01
Singapore 068897

TEL: FAX:
ATTN: Motor Claim Department
Your Ref No : 22/AL/OD-177 (04)
Claim Type : OD CLAIM
Accident Date : 11/04/2022

Claim No :
No :
Date : 12/04/2022
Policy No : SP2000768410-01
Veh Reg No : SMC7609D
Make / Model : Volkswagen Passat
Chassis No : VVVWZZ3CZGE120581
Engine No :
Reg. No :

ESTIMATE FOR VEHICLE NO: SMC7609D

Discription	Quantity	List Price	Amount
Cost Price		SS	SS
1 FRT BONNET (NO STOCK)	1 PC	\$850.00	
2 FRT BONNET HINGE	2PCS	\$190.00	
3 FRT BONNET LOCK	1 PC	\$150.00	
4 FRT BONNET LOCK CATCH	1 PC	\$105.00	
5 FRT BONNET INSULATOR	1 PC	\$150.00	
6 INSULATOR CLIP	8PCS	\$24.00	
7 FRT GRILLE ASSY	1 PC	\$395.00	
8 FRT GRILLE CLIP	4PCS	\$8.00	
9 FRT BUMPER	1 PC	\$950.00	
10 FRT BUMPER RETAINER	2PCS	\$100.00	
11 FRT BUMPER CLIP	10PCS	\$30.00	
12 FRT BUMPER INNER SPONGE	1 PC	\$110.00	
13 FRT BUMPER REINFORCEMENT (NO STOCK)	1 PC	\$460.00	
14 FRT BUMPER LOWER GRILLE	1 PC	\$195.00	
15 FRT BUMPER LOWER GRILLE CHROME	1 PC	\$210.00	
16 NUMBER PLATE GARNISH	1 PC	\$105.00	
17 FRT BUMPER CENTER TOP GARNISH	1 PC	\$175.00	
18 HEADLAMP	2PCS	\$2,800.00	
19 HEADLAMP SUPPORT PANEL	1 PC	\$620.00	
20 HEADLAMP SUPPORT TOP GARNISH	1 PC	\$175.00	
21 SUPPORT TOP GARNISH CLIP	8PCS	\$24.00	
22 BRACE PANEL	1 PC	\$75.00	
23 HEADLAMP PANEL	2PCS	\$130.00	
24 AIRCON CONDENSER (NO STOCK)	1 PC	\$430.00	
25 RADIATOR	1 PC	\$380.00	
26 INTERCOOLER (NO STOCK)	1 PC	\$850.00	
27 RADIATOR MOTOR ASSY	1 PC	\$395.00	
28 AIRCON MOTOR ASSY	1 PC	\$395.00	
29 RADIATOR MOTOR COWLING	1 PC	\$390.00	
30 AIR DUCT	1 PC	\$65.00	
31 AIR HOSE	1 PC	\$125.00	
32 AIR CLEANER BOX	1 PC	\$330.00	
33 WASHER TANK	1 PC	\$120.00	
34 FRT BONNET LOCK CABLE	1 PC	\$65.00	
35 RADIATOR TOP HOSE	1 PC	\$105.00	
36 INTAKE MANIFOLD	1 PC	\$950.00	
37 ALTERNATOR	1 PC	\$1,350.00	
38 TURBO VALVE	1 PC	\$180.00	
39 FRT FENDER	2PCS	\$790.00	
40 HEADLAMP HID UNIT (NO STOCK)	2PCS	\$1,640.00	
41 FRT BUMPER PARKING SENSOR	2PCS	\$460.00	
42 PARKING SENSOR WIRE	1 PC	\$295.00	
		\$17,346.00	
		\$2,601.90	
		\$19,947.90	

Add 15% 102

Special Nett

1	NUMBER PLATE	1 PC	\$40.00	
2	RADIATOR COOLANT	1 PC	\$25.00	

\$65.00

	<u>Labour</u>	
1	WIRE CHECKING	\$30.00
2	REMOVE & REFIX AIRCON AND GAS	\$100.00
3	LABOUR CHARGE	\$700.00
4	SPRAY PAINTING	\$900.00
		\$1,730.00

20
650
880

Amount Before Excess	\$21,742.90
Less Excess	\$0.00
Amount Before GST	\$21,742.90
Add GST @7%	\$1,522.00
Total Amount Payable	\$23,264.90

For SME MOTOR PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

AUTHORISED SIGNATURE