



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					CS3/ASM21012940/Gvy3-1
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Ref: CS3/ASM21012940/Gvy3 Date: 21/12/2021 13/04/2022 Code: ASM		
1. Policy Particulars :- (THIRD PARTY CLAIM)					
Insured Veh.	SHA 2332D		Veh. Inspected	FBR 3360Y	
Policy No.			Coverage (\$)	0.00	
Claim No.	S1M03OXI	LOH Cynthia	Excess (\$)	0.00	
Assign From	DOMINIC YU (SMART CLAIMS)		Assign Date	21/12/2021 13/04/2022	
2. Vehicle Particulars & Condition					
Make & Model			c.c	0	
Engine No.	HIDDEN		Year of Reg.		
Chassis No.			Colour		
Odometer	-		Steering		
Brakes			Modification		
General					
3. Conditions of Tyres					
		Size	Make	Balance	
R/H Front Tyre				mm	
L/H Front Tyre				mm	
R/H Rear Tyre				mm	
L/H Rear Tyre				mm	
4. Description of Damages					
5. General Information					
Accident Date	21/12/2021		Inspection Date	22/12/2021	
Survey held at	149 SHUN LI IND PARK KAKI BUKIT AVE 1 S(416009)				
Repairer	A-TEC AUTOMOTIVE PTE LTD				
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					