



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22003428/Uqy3n2 Date: 20/06/2022 Code: AIS	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLL 177T	Veh. Inspected	SMP 6217P
	Policy No.		Coverage (\$)	0.00
	Claim No.	2022 22004519SL	Excess (\$)	0.00
	Assign From	SHANTI	Assign Date	13/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA GRACE HYBRID (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	GM41206053	Colour	GREY
	Odometer	37074 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/50 ZR16	MAXXIS	6 mm
	L/H Front Tyre	205/50 ZR16	MAXXIS	6 mm
	R/H Rear Tyre	205/50 ZR16	MAXXIS	6 mm
	L/H Rear Tyre	205/50 ZR16	MAXXIS	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	09/04/2022	Inspection Date	23/05/2022
	Survey held at	PROGRESSIVE CAR CARE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	