BIKE PRODUCTION PTE LTD

610, Serangoon Road S(218216) Tel: 63922555, 62995177 Fax: 62975400

ROC/ GST Reg No.: 200007407G

Date: 11 Apr 2022

ASSESSMENT FOR REPAIR: HONDA FS150F - FBN8422R

Chassis No.: Engine No.:

<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front mudguard	\$145.00
1 pc	Front wheel axle	\$75.00
1 pc	Front right brake disk	\$155.00
1 pc	Front left fork assy	\$290.00
1 pc	Front right fork assy	\$290.00
2 pcs	Steering stem bearing	\$90.00
1 pc	Front fork steering stem	\$275.00
1 pc	Front left signal assy	\$55.00
1 pc	Front right signal assy	\$55.00
1 pc	Front cowling inner left	\$105.00
1 pc	Front cowling inner right	\$105.00
1 pc	Front cowling assy	\$135.00
1 pc	Front cowling decals	\$45.00
1 pc	Front downlight assy	\$220.00
1 pc	Headlamp assy	\$295.00
1 pc	Headlamp bracket	\$185.00
1 pc	Left side fairing assy	\$155.00
1 pc	Left side fairing decals	\$45.00
1 pc	Left side black fairing	\$105.00
1 pc	Right side fairing assy	\$155.00
1 pc	Right side fairing decals	\$45.00
1 pc	Right side black fairing	\$105.00
1 pc	Brake lever	\$55.00
1 pc	Clutch lever	\$55.00 \$45.00
1 pc	IU bracket	\$45.00
1 pc	Steering handle Left handle balancer	\$145.00 \$45.00
1 pc	Left riangle balancer Left view mirror	\$45.00
1 pc		\$65.00
1 pc	Right view mirror Headlamp inner black cover	\$65.00
1 pc	•	\$95.00
1 pc	Front inner black cover	\$145.00
1 pc	Left front footrest	\$55.00
1 pc	Left front footrest holder	\$125.00
1 pc	Left rear footrest	\$45.00
1 pc	Left rear footrest holder	\$125.00
1 pc	Subframe assy	\$480.00
1 pc	Left rear cover	\$135.00
1 pc	Left rear cover amblem	\$55.00
1 pc	Left rear cover labels	\$45.00
1 pc	Radiator assy	\$330.00
1 pc	Radiator spare tank	\$145.00
1 pc	Center basket	\$35.00
1 pc	Left rear body cover black	\$90.00
1 pc	Box bracket	\$175.00
	Page 1	

1 pc	wiring harness	\$145.00
1 pc	Head assy	\$495.00
1 pc	Radiator inner cover	\$105.00
1 pc	Gear pedal assy	\$135.00
1 pc	Block and piston assy	\$550.00
1 pc	Exhaust heat shield	\$95.00
1 pc	Swing arm assy	\$395.00
1 pc	Left rear signal	\$55.00
1 pc	Left right signal	\$55.00
1 pc	Exhaust assy	\$580.00
- pc	Extradet doby	Ψ300.00
		\$8,295.00
	Less discount 10%	\$829.50
		\$7,465.50
	Special nett items	ψ, γ, 100.00
1 pc	Coolant	\$50.00
1 pc	Front sport rim	\$395.00
1 pc	Rear sport rim	\$395.00
1 set	Chain and sprockets	\$185.00
1 pc	Top case	\$280.00
1 pc	Front number plate	\$20.00
1 pc	Rear number plate	\$30.00
P -	,	,
1)	Towing charges	\$120.00
-/		Ψ
	Replace, realign and adjust above	
2)	damaged parts, check wiring and	4000 00
2)	lighting system	\$800.00
	To replace and balance front and	
3)	rear wheel rims	\$150.00
	To knock, straighten chassis & body	
4)	balancing	\$450.00
	To remove/refit, replace (if damage) check and	
5)	straighten front fork tubes.	\$150.00
5) 6)	_	\$400.00
6)	Spray painting	\$ 1 00.00
	Total Estimate	\$10,890.50
	. 3441 134111440	Ψ±0,030.30

Note: The above estimate is subjected to the prevailing GST of 7%

For Bike Production Pte Ltd