



# 方商昭噴漆 POON SIANG SEOW

Sin Ming Autocity, No. 160 Sin Ming Drive, #05-13, Singapore 575722.  
Tel: 6453 7511 Fax: 6453 8046 Email: sitti1@singnet.com.sg Regn. No. 05396600K

Leong Hai Peng Daniel  
No 160 sin ming auto city  
Sin ming drive  
Singapore 575722

Not authorized  
L1Png & 3950/h  
Presumy After Paint  
4 days

Dear sir  
Estimate cost of repair to vehicle no. SFD55A  
To supply

|                               |      |          |      |
|-------------------------------|------|----------|------|
| 1. Front bumper               | cm   | 861.90   | ✓    |
| 2. Front bumper reinforcement | R    | 419.85   | X    |
| 3. Front bumper sponge        | cm   | 102.00   | ✓    |
| 4. Front bumper sensor        | SEA  | 350.00   | 2000 |
| 5. Front bumper retainer x2   | ALSP | 139.80   | 4    |
| 6. Front head lamp left       | cm   | 2,315.90 | ✓    |
| 7. Front head lamp moulding   | sn   | 102.00   | X    |
| 8. Front grille 755-20        | mgcm | 885.90   | ✓    |
| 9. Front fog lamp left        | sn   | 381.90   | X    |
| 10. Front fog lamp cover      | sn   | 255.90   | X    |
| 11. Front fender left 890-20  | sn   | 1,089.65 | ✓    |
| 12. Front fender inner garish | sn   | 214.60   | X    |

256

Labour charges  
number plate  
Panel beating  
Spray painting  
Rust proofing  
Total

|    |          |     |
|----|----------|-----|
| sn | 50.00    | X   |
|    | 800.00   | 400 |
|    | 880.00   | 600 |
|    | 100.00   | 30  |
|    | 8,949.40 |     |

Your faithfully

ALBERT POON

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: