




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN : LOH CYNTHIA			Ref: CS3/ASM22003462/Bvy3e2 Date: 11/05/2022 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SGL 2882L	Veh. Inspected	SJF 9190A	
Policy No.	GA566833	Coverage (\$)	0.00	
Claim No.	S2M03YKO	Excess (\$)	0.00	
Assign From	LOH CYNTHIA	Assign Date	14/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA5 5-DOOR WAGON	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6CW1071H0125414	Colour	GREY	
Odometer	80604 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55R16	YOKOHAMA	5 mm	
L/H Front Tyre	205/55R16	YOKOHAMA	5 mm	
R/H Rear Tyre	205/55R16	YOKOHAMA	5 mm	
L/H Rear Tyre	205/55R16	YOKOHAMA	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5. General Information				
Accident Date	13/04/2022	Inspect Date / Time	19/04/2022 (11:21 AM)	
Survey held at	SAU HOCK MOTOR SERVICES BLK 10 ANG MO KIO INDUSTRIAL PARK 2A (AVE 5)#02-14 AMK AUTOPOINT SINGAPORE 568047.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

Report Ref No. CS3/ASM22003462/Bvy3e2

Inspected By

LIM TEOW GUAN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.