



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914			Ref: CS/AWA22003471/Rvy3e2 Date: 09/06/2022 Code: AWA	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 4263B	Veh. Inspected	PA 4430X	
Policy No.	BVF2SB0002782100	Coverage (\$)	0.00	
Claim No.	NSV2200051/PC	Excess (\$)	0.00	
Assign From	STELLA GOH	Assign Date	14/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN URVAN 3.0 M	c.c	2953	
Engine No.	HIDDEN	Year of Reg.	2004	
Chassis No.	JN1TG4E25Z0700685	Colour	GREY	
Odometer	602941 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	BRIDGESTONE	6 mm	
L/H Front Tyre	195 R15C	BRIDGESTONE	6 mm	
R/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm	
L/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/03/2022	Inspection Date	21/04/2022	
Survey held at	SC AUTO INDUSTRIES (S) PTE LTD 51, SENOKO ROAD SINGAPORE 758133			
5a. Remarks				
A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS.. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		