

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	ALLIED WORLD A	SSURANCE COMPANY LTD	Ref:	CS/AWA22003471/Rvy3e2	
	(SINGAPORE BRA 60 ANSON ROAD MAPLETREE ANS SINGAPORE 0799	#08-01 (8th FLOOR) ON	Date	: 28/10/2022	
			Code	e: AWA	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XD 4263B	Veh. Inspected	PA 4430X	
	Policy No.	BVF2SB0002782100	Coverage (\$)	0.00	
	Claim No.	NSV2200051/PC	Excess (\$)	0.00	
	Assign From	STELLA GOH	Assign Date	14/04/2022	
2.	2. Vehicle Particulars & Condition				
	Make & Model	NISSAN URVAN 3.0 M	c.c	2953	
	Engine No.	HIDDEN	Year of Reg.	2004	
	Chassis No.	JN1TG4E25Z0700685	Colour	GREY	
	Odometer	602941 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	FAIR			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195 R15C	BRIDGESTONE	6 mm	
	L/H Front Tyre	195 R15C	BRIDGESTONE	6 mm	
	R/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm	
	L/H Rear Tyre	195 R15C	BRIDGESTONE	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	09/03/2022	Inspection Date	21/04/2022	
	Survey held at	SC AUTO INDUSTRIES (S) PTE LTD			
		51, SENOKO ROAD . SINGAPORE 758133			
5a.					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

10 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: