

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Togs that reconstruction to the reconstruction of the reconstructi					
Affiliated to Federation Internationale Des Experts En Automobile						
	ALLIED WORLD A	SSURANCE COMPANY LTD	F	Ref:	CS/AWA22003471/Rvy3	
	(SINGAPORE BRA 60 ANSON ROAD MAPLETREE ANS SINGAPORE 079	#08-01 (8th FLOOR)	[	Date:	14/04/2022	
			(	Code:	AWA	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	XD 4263B	Veh. Inspected		PA 4430X	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	NSV2200051/PC	Excess (\$)		0.00	
	Assign From	STELLA GOH	Assign Date		14/04/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.		Information				
	Accident Date	09/03/2022	Inspection Date		21/04/2022	
	Survey held at	SC AUTO INDUSTRIES (S) PTE	LTD			
		51, SENOKO ROAD . SINGAPORE 758133				
5a.	5a. Remarks					

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.