

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Yr Regn:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

28/4/22/5# 4530 informed Alex.

Asher

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

not Asher
del

VEHICLE No: SKN 2211R

2/5 \$ 4550
14/4/22

4 days 108

82

1350

1200

380

585

248

Re / torn

scr / surf

R	\$2,201.00	X
del	\$145.00	/
del	\$50.00	/
del	\$102.00	/
11	\$299.00	X
11	\$415.00	X
Re / torn	\$1,455.00	/
Re / torn	\$1,250.00	/
scr / surf	\$480.00	/
su	\$355.00	X
m	\$615.00	/
cra	\$500.00	/
crg	\$170.00	/
shld	\$450.00	/
del	\$50.00	/
11	\$68.00	X
11	\$988.00	X
11	\$365.00	X
11	\$850.00	X
11	\$845.00	X
11	\$1,120.00	X
	\$12,773.00	

(101)

S.NETT

1PC	REAR LICENCE PLATE
1SET	REAR REVERSE CAMERA
1PC	REAR END PANEL SEALANT
1PC	REAR WINDSCREEN SEALANT

Daye	\$50.00	40
su	\$380.00	X
11	\$50.00	X
11	\$50.00	X

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REPLACED REAR PDC SENSOR	\$80.00	50
TO DISMANTLE & REFIX REAR WINDSCREEN	\$120.00	X
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	80
TO DISMANTLE & REFIX REAR EXHAUST	\$100.00	X
TO RESET & DIAGNOSTIC SYATEM	\$280.00	60
TO SPARY RUST PROOFING	\$100.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,200.00	500
TO PUTTY & SPRAY PAINTING	\$1,500.00	750

TOTAL \$16,853.00

P 4670
102
4203

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: