

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6, #02-15@ Kaki Bukit, Singapore 417883

TEL: 6747 6106 (6 lines) Fax: 6744 2368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

LKK Auto Consultants hereby notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and to subject to final approval from Insurance Company

Authorised by Repairer
Signature:
Date:

M/S : Allianz Insurance Singapore Pte Ltd
79 Robinson Road #09-01
Singapore 068897

Claim No :
No :
Date : 14/04/2022
Policy No : SP2000900490
Veh Reg No : SGR9909S
Make / Model : Hyundai Elantra
Chasis No : KMHDH41CMCU215681
Engine No :
Reg. No :

TEL: FAX:
ATTN: Motor Claim Department
Your Ref No : 22/ALJOD-181 (04)
Claim Type : OD CLAIM
Accident Date : 12/04/2022

ESTIMATE FOR VEHICLE NO: SGR9909S

Discription	Quantity	List Price	Amount
Cost Price		S\$	S\$
1 FRT BONNET ✓ BUC	1 PC	\$480.00	
2 FRT BONNET HINGE ?	2PCS	\$60.00	
3 FRT BONNET LOCK ✓ BT	1 PC	\$38.00	
4 FRT GRILLE ASSY ✓ CUT	1 PC	\$105.00	
5 FRT GRILLE CLIP ✓ NEC	4PCS	\$8.00	
6 FRT BUMPER ✓ CRA	1 PC	\$295.00	
7 FRT BUMPER RETAINER X NN	2PCS	\$24.00	
8 FRT BUMPER CLIP ✓ NEC	10PCS	\$20.00	
9 ↘ FRT BUMPER INNER SPONGE ?	1 PC	\$85.00	
10 ↘ FRT BUMPER REINFORCEMENT ?	1 PC	\$155.00	
11 FRT BUMPER LOWER GRILLE ?	1 PC	\$105.00	
12 FOG LAMP GARNISH ?	2PCS	\$40.00	
13 FOG LAMP ?	2PCS	TBC	
14 HEADLAMP ✓ CUT	2PCS	\$700.00	
15 ↘ HEADLAMP SUPPORT PANEL ?	1 PC	\$350.00	
16 ↘ AIRCON CONDENSER ?	1 PC	\$220.00	
17 ↘ RADIATOR ?	1 PC	\$250.00	
18 RADIATOR FAN ASSY ?	1 PC	\$215.00	
19 ↘ AIRCON SIDE DEFLECTOR ?	2PCS	\$36.00	
20 HEADLAMP LOWER BRACKET ✓ NEC	2PCS	\$36.00	
		\$3,222.00	
	Add 10%	\$322.20	\$3,544.20

2778
110%
3055.80

Special Nett

1 FRT NUMBER PLATE ✓ CRA	1 PC	\$40.00	
2 FRT BONNET SEALANT ✓ NEC	1 PC	\$60.00	
			\$100.00 ✓

Labour

1 WIRE CHECKING	\$20.00 ✓
2 REMOVE & REFIX AIRCON AND GAS	\$100.00 ✓
3 LABOUR CHARGE <i>REPLACE SUPPORT - \$600</i>	\$750.00 400
4 SPRAY PAINTING	\$750.00 400
	\$1,620.00

4 Days
Lumpsum repair
After repair photos
Excess: TBA
Not Authorised

1120

Total = 4,275.80

Guo Qiang - LKK	Amount Before Excess	\$5,264.20
	Less Excess	\$0.00
82880282	Amount Before GST	\$5,264.20
	Add GST @7%	\$368.49
	Total Amount Payable	\$5,632.69

US 3400

25/5/22