

ASS. REC. BY:

REF:

GRB / 22003492/ke

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: \$95k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 19 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SM X 36774 Yr Regn: 01, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or WagonMake: Honda Shuttle C.C. 1496Colour: M.P. White A/C: Insured / Std / NI / NASp. Reading: 17817 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GP7 2008792Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: Dayton 185/60R15R: Yoko

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 2 mmL/Bal. 2 mmD.O.A. 8/4/22

Survey held at

Rear

R/Bal. 5 mmL/Bal. 5 mmD.O.I. 14/4/2022

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/SThe U/C / ~~Chassis frame~~ / Body Structure affected due to collision. ✓

Date / Time Action / Instruction

21/12 11am @10,450

29/12 Re-inspection @11,800 Cash

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

✓

Not Authorized
11 By \$11,800
Primary After Paint
14 days

VEHICLE NO: SMX3677Y
CHASSIS NO: GP7-2009792

MODEL: HONDA SHUTTLE

DESCRIPTION		REPAIRER'S ESTIMATE(S\$)	
<u>PARTS (LIST ITEMS)</u>			
REAR BUMPER 985		Tn \$ 1,210.00	✓
REAR BUMPER RETAINER RHS		mit \$ 40.00	✓
REAR BUMPER REFLECTOR		mit \$ 70.00	✓
REAR BUMPER COVER RHS		\$ mit 40.00	✓
TAILGATE		Bz \$ 1,000.00	✓
TAILGATE LAMP LHS		\$ Sn 400.00	x
TAILGATE LAMP RHS		Bz \$ 400.00	✓
TAILGATE WEATHERSTRIP		Dil/DL \$ 120.00	✓
TAILGATE LOCK ASSY		Tn \$ 180.00	✓
TAILGATE INNER TRIM		Bz \$ 210.00	✓
TAIL GATE CENTRE GARNISH (CHROME) 428		mycm \$ 480.00	✓
HONDA EMBLEM		\$ me 50.00	✓
SHUTTLE EMBLEM		na \$ 60.00	x
REAR WINDSCREEN		shotover \$ 1,240.00	✓
REAR WINDSCREEN MOULDING		me \$ 100.00	✓
REAR WIPER MOTOR		Sn \$ 380.00	x
REAR WIPER ARM		Sn \$ 80.00	x
REAR SPOILER WING		Sn \$ 1,220.00	x
THIRD BRAKE LAMP		Sn \$ 230.00	x
TAIL LAMP LHS		Sn \$ 410.00	x
TAIL LAMP RHS		Bz \$ 410.00	✓
TAIL LAMP PANEL RHS		\$ Bz 200.00	✓
END PANEL		\$ Bz 460.00	✓
END PANEL TOP GARNISH		mycm \$ 110.00	✓
SPARE TYRE PANEL		Bz \$ 990.00	✓
SPARE TYRE TOP COVER		Bz/nd \$ 460.00	✓
SPARE TYRE TOOL BOX SPONGE		Sc \$ 100.00	x
REAR FRAME STIFFENER RHS		\$ Sn 280.00	x
REAR FENDER LHS		Bz \$ 910.00	✓
REAR FENDER INNER SHIELD RHS		mit \$ 100.00	✓
REAR FENDER PILLAR TRIM (UPPER)		Sn \$ 220.00	x

REAR FENDER INNER TRIM LHS
 REAR WHEELHOUSE PANEL LHS
 REAR QUARTER GLASS RHS 308
 REAR QUARTER GLASS MOULDING RHS
 REAR DOOR LHS
 REAR SIDE FRAME RHS (UPPER)
 ROOF
 ROOF LINING
 ROOF GARNISH RHS
 REAR SEAT BELT ASSY RHS
 REAR SPORTS RIM RHS
 ROOF GARNISH LHS
 REAR BUMPER SPONGE RHS
 SPARE TYRE STORAGE COVER
 SPARE TYRE STORAGE COVER DOOR
 TAILGATE ABSORBER
 TAILGATE HINGE LHS
 TAILGATE HINGE RHS
 REAR FENDER INNER TRIM RHS (UPPER)
 REAR FENDER AIR GUIDE RHS
 REAR WHEELHOUSE PANEL UPPER
 ROOF

Bu	\$	360.00	✓
Bu	\$	680.00	✓
Photocopy	\$	500.00	✓
bu	\$	200.00	✓
R	\$	910.00	X
R	\$	960.00	X
R	\$	1,080.00	X
bu	\$	1,130.00	X
bu	\$	150.00	X
	\$	600.00	X
bu	\$	500.00	250/12
bu	\$	150.00	X
CM	\$	80.00	✓
	\$	300.00	X
	\$	100.00	X
	\$	200.00	X
	\$	80.00	X
	\$	80.00	X
bu	\$	120.00	X
CM	\$	80.00	✓
	\$	250.00	X
R	\$	1,080.00	X

	\$ 21,750.00
20%	\$ 4,350.00
	\$ 17,400.00

SPECIAL NETT ITEMS

REAR SENSORS
REAR BUMPER CLIPS 1 SET
DASH CAMERA
CARPLATE W/HOLDER
CEREMIC COATING

TS
\$ 200.00 ✓
na
\$ 60.00 ✓
mis *le*
\$ 300.00 *X* ✓
in
\$ 60.00 *X*
(Bill) *\$nn* 600.00 *X*

Total \$ 1,220.00

TOTAL PARTS \$ 18,620.00

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)
	<u>LABOUR</u>	
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 2,500.00 <i>2000</i>
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 2,200.00 <i>1800</i>
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ 100.00 <i>20</i>
4	To provide anti-rust treatment on affected areas	\$ 100.00 ✓
5	Remove and refit rear windscreen	\$ 150.00 <i>120</i>
6	Remove and refit rear quarter glass	\$ 150.00 <i>60</i>
7	Remove and refit roof lining	\$ 200.00
8	Remove and refit rear upholstery	\$ 300.00 <i>150</i>
9	Transfer tailgate parts	\$ 150.00 <i>60</i>
	Labour Total :	\$ 5,850.00
	TOTAL (PARTS & LABOUR):	\$ 24,470.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MODEL: HONDA SHUTTLE

DESCRIPTION		REPAIRER'S ESTIMATE(S\$)	
<u>PARTS (LIST ITEMS)</u>			
REAR AXEL	1080	R	\$ 1,120.00 ✓
REAR ABSORBER LHS		\$ R	280.00 ✓
REAR ABSORBER SPRING LHS		L	\$ 300.00 X
REAR WHEELHUB W/BEARING LHS		R	\$ 300.00 ✓
		20%	\$ 2,000.00
			\$ 400.00
			\$ 1,600.00
<u>SPECIAL NETT ITEMS</u>			
TOTAL:		\$	-
TOTAL PARTS		\$	1,600.00

<u>LABOUR</u>			
REMOVE & REFIT REAR UNDERCARRIAGE LHS		\$ 200.00	1801
REMOVE & REFIT HYBRID BATTERY		\$ 300.00	2001
REAMOVE & REFIT REAR AXEL		\$ 200.00	X
	TOTAL:	\$ 700.00	
(LABOUR + PARTS) TOTAL:		\$ 2,300.00	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	507D

Vehicle Details

Vehicle No.:	SMX3677Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	12 Apr 2022
Vehicle Make:	HONDA
Vehicle Model:	SHUTTLE HYBRID 1.5 AUTO
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	LEB7112234
Chassis No.:	GP72009792
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$23,626.00
Original Registration Date:	08 Jan 2021
First Registration Date:	08 Jan 2021
Transfer Count:	1
Actual ARF Paid:	\$10,077.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Jan 2031
PARF Rebate Amount:	\$7,557.00

Intended COE Rebate Details

COE Expiry Date:	07 Jan 2031
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$45,012.00
COE Rebate Amount:	\$36,009.00
Total Rebate Amount:	\$43,566.00

The information contained herein is correct as at 12 Apr 2022

OK