



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI22003500/Avy3e2	
			Date: 25/05/2022	
			Code: UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKT 3027T	Veh. Inspected	SJG 3330Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	M12D18222205	Excess (\$)	0.00	
Assign From	WONG JOSEPHINE	Assign Date	18/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	MR053HY9305076253	Colour	BLUE	
Odometer	203387 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	MICHELIN	6 mm	
L/H Front Tyre	185/60 R15	MICHELIN	6 mm	
R/H Rear Tyre	185/60 R15	MICHELIN	6 mm	
L/H Rear Tyre	185/60 R15	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/04/2022	Inspection Date	18/04/2022	
Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	