



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KHOR SAW THENG			Ref: CC4/ASM22003504/Apa3q2 Date: 20/01/2023 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLP 3675G	Veh. Inspected	SKW 2953K
	Policy No.	GA212513	Coverage (\$)	0.00
	Claim No.	S2M03YKL	Excess (\$)	0.00
	Assign From		Assign Date	18/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA VIOS	c.c	1497
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	MR053HY9305122376	Colour	RED
	Odometer	263635 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/60 R15	YOKOHAMA	6 mm
	L/H Front Tyre	195/60 R15	YOKOHAMA	6 mm
	R/H Rear Tyre	195/60 R15	YOKOHAMA	6 mm
	L/H Rear Tyre	195/60 R15	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	14/04/2022	Inspection Date	18/04/2022
	Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	