

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Document No.

: SQT22000962

Page

QUOTATION

GST Reg No.: M200050223 Company Ref. No.: S60FC1380G

8 SHENTON WAY

)

: 9. Apr 2022 Customer No. : WZA006

#27-01 AXA TOWER SINGAPORE 068811

: AXA INSURANCE PTE LTD .

Svc Advisor : NG SIN HAI

Registration No : SMD2876B **Engine No** Date | Time

Date

Qty

: L15B4534155 : 9. Apr 2022 10:31:59 AM

Chassis No Model

Customer

: JHMRU1830GX204155 : HRV LX-SIN CVT YM 2016

Surveyor Name

Owner's Name

ltem

: HAMISH JOSEPH WINSTANLEY

Survey Date

Authorisation Date

Unit Price Disc %

Ins Policy No. Date of Accident

: 8/4/2022

Description TP DIRECT SETTLEMENT (J/NO 0% GST **Amount**

Amount incld GST

OWNER:

OWNER INSURER:

ACC DATE:

SURVEYED BY:

	DATE:					
	REF NO:					
	TP INSURER:					
	TP VEH:					
BOSUN	SUNDRIES	1	110.00	110.00	7.70	117.70
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	220.00	220.00	15.40	235.40
BOJSE	BODY JOINT SEALANT REAR END PANEL	1	120.00	120.00	8.40	128.40
BOJSE	BODY JOINT SEALANT REAR FLOOR PANEL	1	120.00	120.00	8.40	128.40
BOJSE	BODY JOINT SEALANT TAILGATE	1	120.00	120.00	8.40	128.40
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	220.00	220.00	15.40	235.40
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	650.00	650.00	45.50	695.50
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	650.00	650.00	45.50	695.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00	650.00	45.50	695.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	650.00	650.00	45.50	695.50
BODAMKIT	WINDSCREEN DAM KIT.	1	120.00	120.00	8.40	128.40
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN	1	5500.00	5500.00	385.00	5885.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (6P)	^{3.} 1	3200.00	3200.00	224.00	3424.00
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	450.00	450.00	31.50	481.50
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	650.00	650.00	45.50	695.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	650.00	650.00	45.50	695.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00	650.00	45.50	695.50

Printed on 9/4/2022 11:01:56 AM

This is a computer generated invoice. No signature is required.


Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.





KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Document No.

: SQT22000962

Page 2

QUOTATION

Company Ref. No.: S60FC1380G

GST Reg No.: M200050223

8 SHENTON WAY

#27-01 AXA TOWER SINGAPORE 068811

: AXA INSURANCE PTE LTD

Date

: 9. Apr 2022 : WZA006

Svc Advisor

: NG SIN HAI : L15B4534155

Registration No : SMD2876B

Engine No Date | Time

Customer No.

: 9. Apr 2022 10:31:59 AM

Chassis No Model

Customer

: JHMRU1830GX204155 : HRV LX-SIN CVT YM 2016

Surveyor Name

Owner's Name

: HAMISH JOSEPH WINSTANLEY

Survey Date

Ins Policy No.

Authorisation Date

Date of Accident

: 8/4/2022

Item	Description	Otro	Unit Deine	D: 0/	*************	0% GST Amount	Amount incld GST
BOSUN	REMOVE AND RE-INSTALL TAILGATE SPOILER	Qty 1	Unit Price 480.00	Disc %	480.00	33.60	513.60
BP00R	APPLY BODY UNDERSIDE COATING (N).	4	520.00		520.00	36.40	556.40
	7 11 1 2 2 2 3 1 3 1 2 1 3 2 1 3 3 1 1 1 1			Sum Labor	<u>15730.00</u>	1,101.10	16.831.10
			,	Juin Labor	10700.00	1,101.10	10.031.10
RS-TMP3040L	VPC 4PCS REAR SENSORS	1	320.00		320.00	22.40	342.40
33502-T7A-J01	LAMP UNITR.	1	503.90	25	377.92	26.45	404.37
33552-T7A-J01	LAMP UNITL.	1	503.90	25	377.92	26.45	404.37
34150-T7A-J01	LIGHT ASSY,R.LID	1	287.80	25	215.85	15.11	230.96
34155-T7A-J01	LIGHT ASSYL.LID	1	287.80	25	215.85	15.11	230.96
68100-T7A-J20ZZ	TAIL GATE COMP	1	912.60	25	684.45	47.91	732.36
74440-T7A-003	WEATHERSTRIPTAILGATE	1	105.20	25	78.90	5.52	84.42
74800-T7A-J02	LOCK ASSYTAILGATE	1	90.10	25	67.57	4.73	72.30
84431-T7A-J01ZA	LINING ASSYTAILGATE	1	145.10	25	108.82	7.62	116.44
75722-T7W-A01	EMBLEMRR.	1	15.20	25	11.40	0.80	12.20
33505-T7A-J01	REFLECTOR ASSYR.RR.	1	178.50	25	133.87	9.37	143.24
33555-T7A-J01	REFLECTOR ASSYL.RR.	1	178.50	25	133.87	9.37	143.24
04717-T7A-000ZZ	FACER.RR.BUMPER CORNER	1	105.50	25	79.12	5.54	84.66
04718-T7A-000ZZ	FACEL.RR.BUMPER CORNER	1	105.50	25	79.12	5.54	84.66
71593-T7A-000	SPACER,R.RR.BUMPER SIDE	1	18.00	25	13.50	0.95	14.45
71598-T7A-000	SPACER,L.RR.BUMPER SIDE	1	18.00	25	13.50	0.95	14.45
91505-TM8-003	CLIP,BUMPER	8	2.30	25	13.80	0.97	14.77
66100-T7A-300ZZ	PANEL COMPRR.	1	397.90	25	298.42	20.89	319.31
84640-T7A-J01ZA	LINING ASSYRR.PANEL	1	46.80	25	35.10	2.46	37.56
04655-T7A-310ZZ	PANEL SET,RR.FLOOR	1	720.30	25	540.22	37.82	578.04
72841-SH3-315	OILSHEET	3	43.40	25	97.65	6.84	104.49
73214-T7J-H01	RUBBER CR.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
73226-SZW-000	DAMPERSTD 5X5	1	9.10	25	6.82	0.48	7.30
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT	1	5.20	25	3.90	0.27	4.17

Printed on 9/4/2022 11:01:56 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co., Sdn., Bhd, it will be refunded.





KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Document No.

: SQT22000962

Page

21,203.52

21,203.52

3

QUOTATION

Company Ref. No.: S60FC1380G

GST Reg No.: M200050223

8 SHENTON WAY

#27-01 AXA TOWER

Customer No.

Date

9. Apr 2022 WZA006

Total Amount 19,816.36 1,387.16

SINGAPORE 068811

: AXA INSURANCE PTE LTD

: NG SIN HAI Svc Advisor

Registration No

: SMD2876B

: L15B4534155

Chassis No

Engine No Date | Time

Model

Customer

: JHMRU1830GX204155

: HRV LX-SIN CVT YM 2016

Surveyor Name

9. Apr 2022 10:31:59 AM

Owner's Name

: HAMISH JOSEPH WINSTANLEY

Survey Date

Total (Inclusive of GST)

Ins Policy No. **Date of Accident**

:

: 8/4/2022

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
91501-S70-003	FASTENER BW/SHIELD	4	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B	2	5.50	25	8.25	0.58	8.83
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
				Sum Item	4086.36	286.06	4,372.42
Survey By							

Survey By		
Date & Time		
Excess		
Status	2	
Signature		

Printed on 9/4/2022 11:01:56 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 09/04/2022 10:30 (SGT) Date of Accident 08/04/2022 17:40 (SGT) Exact Location of Accident Singapore Additional Location Information **CLEMENTI ROAD** Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMD2876B

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner HAMISH JOSEPH WINSTANLEY NRIC No SXXXX747Z Email Address HAMISHWINSTANLEY@GMAIL.COM Mobile Phone No (Phone) +65-93209004 Alternative Phone No (Home) +65-93209004

VEHICLE PARTICULARS

Manufacturer Honda Model Variant Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Private car Transmission Auto 1500

INSURANCE COMPANY

Name of Insurance Company Tokio Marine Insurance Singapore Ltd Type of Coverage Comprehensive Fleet Policy No Policy Number Cover Note Number

DRIVER

HAMISH JOSEPH WINSTANLEY SXXXX747Z

Date Of Birth Occupation Date Of Driving Pass Driving experience Gender Mobile Number Alt. Phone Number Email Address Address Address Address Address complement Postcode Is the driver the policyholder? If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver	25/09/1986 Indoor 02/09/2010 11 YEARS AND 7 MONTHS Male (Phone) +65-93209004 (Home) +65-93209004 HAMISHWINSTANLEY@GMAIL.COM S - - - Yes
Insurance Company of Other Vehicle Owned by Driver	-
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident Weather Conditions Road Surface	Collision - Head to Rear Clear Dry
OTHER INFORMATION	
Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No 2 No - Yes 2
PASSENGER 1 Name Gender	HOON SHU MEI SUMATHI Female
DETAILS OF POLICE ACTION	
Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom?	No No
CIRCUMSTANCES OF ACCIDENT	
REFER	
ATTACHMENT(S)	
Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded?	Yes Yes No
DETAILS OF OTHER	R VEHICLE PROPERTY 1
Vehicle Registration Number Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category	SMA4964H Private car

Name of Driver	
Contact Number	-
Address	-
Address complement	1
Postcode	-
Insurance Company Name	_
Nature Of Damage	_
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3, Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy kability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims:
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims,

(collectively the "Purposes")


- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Date 8. Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident	
	0.1
I was driving along Clementi flood when the traffic lies at Nger Ann Poly changed to red. I came to a gradual stop as the first car to reach the light. The rear of my car was het a few seconds later by car SMA 4964H. This caused my car to be pushed forward a couple of motion. There was extensive damage caused to the rear of my car:	y lads
at Ngex Ann Poly changed to red I came to a gradual	
stop as the first car to reach the light. The rear of my	
car was het a few seconds later by car SMA 4964H.	
This caused my car to be pushed forward a couple of	_
metres. There tras extensive damage caused to the rear	
of my car.	
The driver of the car that hit me got out and	
The driver of the car that hit me got out and said "it sorry, it's my fault, lost concentration" and we the	in
exchanged debails	
	_
	- 0
	_
	-5
100 100 100 100 100 100 100 100 100 100	

Declaration

IWe declare the foregoing particulars are true in every respect.

Policyfiolder's Signature / Date & Time

Oriver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

9/4/22 8:50 am.

