

FASTECH AUTO PTE LTD
 1 Kaki Bukit Ave 6 #01-48 Autobay
 Singapore 417883
 Tel No: 67452063/ 67467158 Fax No: 67458520
 Tax Reg No : 200006262D

HSIAO Tony

not Authorised

18/4/22

2/s \$2000/
 4 days.

VEHICLE No: GBB 5697Y

NETT ITEM

1PC TAILLAMP N/S
 1PC TAILLAMP HOUSING PANEL N/S
 1PC REAR FENDER N/S
 1PC REAR BUMPER
 1PC REAR BUMPER RETAINER N/S
 1SET REAR BUMPER CLIPS
 1PC REAR END PANEL

one \$224.80 ✓
 R \$488.20 X
 R \$2,010.30 X
 693.20 715 \$894.20 ✓
 one \$45.00 ✓
 one \$39.00 ✓
 R \$445.10 X
 \$4,146.60

102

S.NETT

1SET REAR FENDER CORPORATE STICKER N/S
 1SET TAILGATE CORPORATE STICKER
 1SET TAILGATE '70km/h & 8 pax' STICKER
 1PC TAILGATE '3.0D' STICKER

one \$480.00 200
 one \$300.00 150
 one \$20.00 ✓
 one \$25.00 ✓

TO CHECK WIRING
 TO DISMANTLE & REFIX REAR REVERSE SENSOR
 TO SPRAY RUST PROOFING
 LABOUR FOR PANEL BEATING & REPLACED PARTS
 TO PUTTY & SPRAY PAINTING

\$50.00 20
 \$80.00 50
 11 \$50.00 X
 \$800.00 400
 \$1,080.00 750

TOTAL \$7,031.60

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-1002
 102
 9-901-80
 S-N-395
 2-1220
 2576.60
 204
 2013