

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/AIG22003515/Uea3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

LTA 1974

Vehicle: IN / OUT

Veh No:

FBN7222H

Yr Regn:

27/11/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda CB400SF c.c 399

Colour

Black

A/C:

Insured / Std / NI / NA

Sp.Reading

45447

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NC 42/901267

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

120/70ZNR17

R:

160/60ZNR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

mm

Rear

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

13/04/22

D.O.I.

18/04/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Fr, 1/5 Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Rep 2500

10/5/22 2/5 @ 6700 informed MR200.

Hi new system can't proceed.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) ___ S + RS, ___ SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

)

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

AIG

Name : Muhammad Haikel Bin
Mohammed Hussein
(86882428)

Accident Date : 13-Apr-22

Vehicle No : FBN7222H

Vehicle Model : Honda CB400SF
Manual

Estimated Repair Costs

Qty	Description	Amount S(\$)
<u>List Items</u>		
1	Front fender CNA	198 \$ 298.00
2	Fork inner tubes SLC	\$ 1,120.00 X
2	Fork outer tuber SLC	\$ 1,140.00 X
1	Fork under bracket n7	\$ 385.00 X
1	Front sport rim Bent/worn	980 \$ 1,100.00
2	Front brake discs AN	\$ 1,120.00 X
1	Front rim shaft SLC	\$ 68.00 X
1	Front rim bearing net	\$ 58.00
1	Headlamp (LED) CNA	\$ 1,380.00
1	Meter assy CNA	1850 \$ 1,880.00
1	Windshield CNA	288 \$ 328.00
1	Top cowling CNA	\$ 380.00
1	Handle bar Bent	\$ 145.00
1	Handle bar end (1 set) CNA	\$ 50.00
1	Hand grip (1 Set) n7	\$ 60.00 X
2	Side mirrors MSB20	95 \$ 260.00 1pc
1	Clutch lever CNA	125 \$ 180.00
2	Front signals MS CNA	85 \$ 390.00 1pc
1	Fuel tank DO	1350 \$ 1,680.00
1	Front footrest n7	320/mis 60 \$ 190.00
1	Front footrest bracket n7	CNA 210 \$ 280.00
1	Rear footrest SLC	\$ 170.00 X
1	Gear pedal Bent	140 \$ 285.00
1	Engine cover CNA	\$ 480.00
1	Side fairing Bent CNA	\$ 285.00
		\$ 13,712.00
Less 10%		\$ 1,371.20
		\$ 12,340.80

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Name : **Muhammad Haikel Bin
Mohammed Hussein**
(86882428)

Accident Date : **13-Apr-22**

Vehicle No : **FBN7222H**

Vehicle Model : **Honda CB400SF
Manual**

Estimated Repair Costs

Special Nett Items

1	Number plate (1 set)	1 1	\$	38.00	X
2	Fork oils	1 1	\$	30.00	X
2	Fork oil seals	1 1	\$	56.00	X
1	Steering cone (1 set)	1 1	\$	125.00	X
1	Rear box	1 1	\$	680.00	480
1	Rear box bracket	1 1	\$	180.00	X
1	E.R.P.IU	1 1	\$	180.00	X
1	Crash bar (1 set)	1 1	\$	420.00	280
			\$	1,709.00	

S/No.

Labour

1	To provide towing service (LOD) \$35.00	refer LOD	\$	-	
2	To check wiring and reset headlamp focusing		\$	1 1 80.00	X
3	To provide labour		\$	600.00	380
4	To repair body frame		\$	1 1 520.00	X
			\$	1,200.00	

Grand Total

\$ 15,249.80

Singapore Dollars: Fifteen Thousand Two Hundred Forty-Nine and Cents: Eighty only

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: