



# 簡福星摩嘜王廠

## KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

ALLIANZ INSURANCE SINGAPORE PTE LTD

DATE : 26-04-2022

79 ROBINSON ROAD

#09-01

SINGAPORE 068897

VEHICLE NO. : SMA9140K

ACCIDENT DATE : 14-04-2022 18:15

THIRD PARTY REF. : SHC1133H

ATTN: MOTOR CLAIMS DEPT.

SUPPLEMENTARY COST OF REPAIR TO VEICLE SMA9140K HONDA SHUTTLE 1.5G CVT ABS D/AIRBAG

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	FRONT GRILLE BRACKET cut	35.00
1	FRONT FENDER RH bent	145.00
1	FRONT FENDER TOP BRACKET RH cut	38.00
1	WASHER TANK cut	50.00
1	WASHER TANK NECK cut	10.00
1	WASHER TANK NECK COVER cut	8.00
1	FRONT WIPER GARNISH cut	140.00
1	FRONT WIPER CORNER GARNISH RH cut	10.00
1	RADAIOR SPARE TANK cut	20.00
1	FRONT BUMPER SIDE CUT cut	18.00
1	Radiator Fan Cowling \$55.00 broken	529.00
	ADD 10 %	52.90
	TOTAL ( A )	581.90
	SUPPLEMENTARY TOTAL	581.90