



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22003524/Kty3e2 Date: 28/04/2022 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 5795B	Veh. Inspected	SMP 582Z
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/04/22/2031	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	18/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALTIS (A)	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	MR053REH104527448	Colour	METALLIC PEARL WHITE
	Odometer	347797 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	PIRELLI	4 mm
	L/H Front Tyre	205/55 R16	PIRELLI	4 mm
	R/H Rear Tyre	205/55 R16	PIRELLI	8 mm
	L/H Rear Tyre	205/55 R16	PIRELLI	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	12/04/2022	Inspection Date	20/04/2022
	Survey held at	YEE AUTO PTE LTD 160 SIN MING DRIVE #02-17 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	