

ASS. REC.

1107

For



# YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/07-12 Sin Ming AutoCity Singapore 575722  
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031  
Email: yeeautopteltd@gmail.com  
Registration No.: 201719251W GST No: 201719251W

M/S : First Capital Insurance Ltd  
36 Robinson Road  
#16-01 City House  
Singapore 068877

ATTN: Motor Claim Department

Your Ref No: -  
Claim Type: Third Party  
Accident Date: 12/04/2022  
TP Veh Reg No: SHB5795B

*Not Notified  
11pm @ 2100hr  
Penny After 10pm  
5days*

Estimate No: ES2200003  
Date: 19 Apr 2022  
Policy No:  
Veh Reg No: SMP582Z  
Make/Model: TOYOTA TOYOTA  
COROLLA ALTIS 1.6L  
CVT  
Chassis No: MR053REH104527448  
Engine No: 1ZR492179  
Reg. Date: 12/03/2015

## Estimate Repair Cost to Vehicle No :SMP582Z

| Description                                                          | U/Price  | Quantity | List Price | Amount          |
|----------------------------------------------------------------------|----------|----------|------------|-----------------|
|                                                                      |          |          | SS         | SS              |
| <b>Net Price</b>                                                     |          |          |            |                 |
| 1 REAR TYRE - RH                                                     | 300.00   | 1 PC     | 300.00     | <i>250.00</i> X |
| 2 REAR WHEEL RIM - RH                                                | 800.00   | 1 PC     | 800.00     | <i>250.00</i>   |
|                                                                      |          |          | 1,100.00   | 1,100.00        |
| <b>Spare Parts</b>                                                   |          |          |            |                 |
| 3 FRONT DOOR - RH                                                    | 955.00   | 1 PC     | 955.00     | X               |
| 4 FRONT DOOR STICKER - RH                                            | 75.00    | 1 PC     | 75.00      | X               |
| 5 FRONT DOOR WEATHERSTRIP - RH                                       | 135.00   | 1 PC     | 135.00     | X               |
| 6 REAR AXLE                                                          | 980.00   | 1 PC     | 980.00     | X               |
| 7 REAR BUMPER                                                        | 842.90   | 1 PC     | 842.90     | X               |
| 8 REAR BUMPER SIDE RETAINER - LH                                     | 80.00    | 1 PC     | 80.00      | X               |
| 9 REAR BUMPER SIDE RETAINER - RH                                     | 80.00    | 1 PC     | 80.00      | X               |
| 10 REAR DOOR - RH                                                    | 969.30   | 1 PC     | 969.30     | ✓               |
| 11 REAR DOOR HINGE - RH (TOP)                                        | 71.50    | 1 PC     | 71.50      | X               |
| 12 REAR DOOR HINGE - RH (LOWER)                                      | 71.50    | 1 PC     | 71.50      | X               |
| 13 REAR DOOR LOCK - RH                                               | 361.20   | 1 PC     | 361.20     | X               |
| 14 REAR DOOR OUTER HANDLE - RH                                       | 183.90   | 1 PC     | 183.90     | X               |
| 15 REAR DOOR REGULATOR GEAR - RH                                     | 261.20   | 1 PC     | 261.20     | X               |
| 16 REAR DOOR STICKER - RH                                            | 75.00    | 1 PC     | 75.00      | ✓               |
| 17 REAR DOOR TRIMBOARD CLIPS - RH                                    | 50.00    | 1 SET    | 50.00      | X               |
| 18 REAR DOOR TRIM BOARD - RH                                         | 568.20   | 1 PC     | 568.20     | X               |
| 19 REAR DOOR WEATHERSTRIP - RH                                       | 135.60   | 1 PC     | 135.60     | X               |
| 20 REAR SHOCK ABSORBER - RH                                          | 335.50   | 1 PC     | 335.50     | ✓               |
| 21 REAR STEP GARNISH - RH                                            | 261.20   | 1 PC     | 261.20     | X               |
| 22 REAR WHEEL BEARING - RH                                           | 220.00   | 1 PC     | 220.00     | ✓               |
|                                                                      |          |          | 6,712.00   | 6,712.00        |
| <b>Labour</b>                                                        |          |          |            |                 |
| 23 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY. | 1,400.00 | 1 JOB    | 1,400.00   | <i>500</i>      |
| 24 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.     | 1,400.00 | 1 JOB    | 1,400.00   | <i>660</i>      |
| 25 TO REMOVE/TRANSFER RH FRONT AND REAR DOOR MECHANISMS.             | 150.00   | 1 JOB    | 150.00     | <i>60</i>       |
| 26 TO CHECK WIRING FUNCTIONS.                                        | 80.00    | 1 JOB    | 80.00      | <i>20</i>       |
| 27 WHEEL ALIGNMENT                                                   | 120.00   | 1 T      | 120.00     | <i>60</i>       |

9862

Acknowledged by Repairer  
Signature:  
Date: