



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 ATTN: JEFFREY NG		Ref: CS3/AIG21013318/Gty3e2-1 Date: 12/05/2022 Code: AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMX 1339L	Veh. Inspected	FBS 3812E
Policy No.	7990000020	Coverage (\$)	0.00
Claim No.	3144170637SG	Excess (\$)	0.00
Assign From	JEFFREY NG	Assign Date	18/04/2022
2. Vehicle Particulars & Condition			
Make & Model	YAMAHA XMAX	c.c	250
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	MH3SG3910MK035611	Colour	BLUE
Odometer	21286 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	120/70-15	PIRELLI	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	140/70-14	PIRELLI	6 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	24/12/2021	Inspection Date	30/12/2021
Survey held at	GP MOTORING PTE LTD 282 MACPHERSON ROAD SINGAPORE 348607		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	