



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22003660/Evy3m4 Date: 28/09/2022 Code: AIS	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMG 6158Z	Veh. Inspected	SCR 6500D
	Policy No.	SP2001285770-01	Coverage (\$)	0.00
	Claim No.	2022 22004569SL	Excess (\$)	0.00
	Assign From	FLORA QUEK	Assign Date	20/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	BMW M4	c.c	2979
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	WBS3R92010K340887	Colour	SILVER
	Odometer	58194 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	265/35 ZR19	MICHELIN	5 mm
	L/H Front Tyre	265/35 ZR19	MICHELIN	5 mm
	R/H Rear Tyre	265/35 ZR19	MICHELIN	5 mm
	L/H Rear Tyre	265/35 ZR19	MICHELIN	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/04/2022	Inspection Date	20/04/2022
	Survey held at	BIS AUTOMOBILES PTE LTD 30 TEBAN GARDENS CRESCENT, SINGAPORE 608927		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	