Meng Yan (LKK Auto)

From: Claims <claims@budgetdirect.com.sg>
Sent: Wednesday, 20 April, 2022 12:35 PM

To: Summer (LKK Auto); sur@lkkauto.com; assignments@lkkauto.com

Cc: Derrick Quok; Kenneth Lim; Julie Mangubat

Subject: TPPD survey: Claim ref: C10014807/JM || OI-SLM4071H (White) TP-SGW6779T || Est:

\$0.00 || M-Tech Motor Services

Attachments: TP Report SGW6779T.pdf; OI Report SLM4071H.pdf; TP report.PNG

Hi Team

We wish to appoint LKK to conduct survey for the TP vehicle number: SGW6779T

M-Tech Motor Services Blk 9005 Tampines St 93 #01-252 Singapore 528839

Tel: 67840077

Attached GIA reports.

Thank you.

Warmest Regards,

Shafawati Md Rabu Admin Executive, Claims

T +65 6989 3697 **F** +65 6725 0853

E shafawati.m@budgetdirect.com.sq



Customer Care +65 6221 2111 **Claims** +65 6221 2199 **Claims (Int.)** +65 6540 2199

190 Clemenceau Avenue, #03-01 Singapore Shopping Centre Singapore 239924

budgetdirect.com.sq



Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **<u>Budget</u> <u>Direct Insurance</u>**.

From: Kuru & Co <kurulegal@yahoo.com.sg> Sent: Wednesday, 20 April 2022 10:19 AM To: Claims <claims@budgetdirect.com.sg>

Subject: Re: PRI Request on 18/04/2022 | C10014807 | PRE-REPAIR NOTIFICATION: OUR REF: L.22.0291.JT (CJ) -

ACCIDENT INVOLVING SGW 6779T AND SLM 4071H (YOUR INSURED)...

Dear Sir,

We refer to your email of 19 April 2022.

Our client is agreeable to the following surveyor(s) as the SJE: LKK Auto Consultants Pte Ltd

Please arrange for your surveyor to survey our client's vehicle at the following address:

M-Tech Motor Services Blk 9005 Tampines St 93 #01-252 Singapore 528839 Tel: 67840077

Please instruct your surveyor to conduct the pre-repair survey **immediately** and complete the pre-repair survey within 2 working days of his appointment.

Kindly let us have the pre-repair and/or post repair survey report upon completion of the survey(s).

As solicitors on record, our client shall look to you for payment of our legal costs plus disbursements should you reach a direct settlement with our client's repairer.

Thank you and regards,

Ms Ting Kuru & Co 150 South Bridge Road #04-06 Fook Hai Building Singapore 058727

Tel: 6532 2009 Fax: 6532 2007

CONFIDENTIALITY CAUTION: This message is intended for the addressee(s) only and may contain confidential information and/or may be subjected to legal privilege. If you have received in error, please notify us immediately by return email, delete this message and you shall not disseminate, distribute or copy any information contained herein.

From: Kuru & Co < kurulegal@yahoo.com.sg Sent: Monday, 18 April 2022 12:34 PM
To: Claims < claims@budgetdirect.com.sg>

Subject: PRE-REPAIR NOTIFICATION: OUR REF: L.22.0291.JT (CJ) - ACCIDENT INVOLVING SGW 6779T AND

SLM 4071H (YOUR INSURED) ON 17.04.2022

ACCIDENT INVOLVING SGW 6779T AND SLM 4071H ON 17.04.2022

AT/ALONG UPPER CHANGI ROAD

NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY

NOTIFICATION OF ACCIDENT AND PRE-REPAIR SURVEY
Dear Sirs,
We act for Budi Santoso, whose vehicle registration number SGW 6779T was damaged in the above accident
A copy of the Singapore Accident Statement filed is enclosed.
As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle.

If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Regards

Judy Tan

Kuru & Co 150 South Bridge Road #04-06 Fook Hai Building Singapore 058727

Tel: 6532 2009

Fax: 6532 2007

CONFIDENTIALITY CAUTION: This message is intended for the addressee(s) only and may contain confidential information and/or may be subjected to legal privilege. If you have received in error, please notify us immediately by return email, delete this message and you shall not disseminate, distribute or copy any information contained herein.