



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914		Ref: CS3/AWA21008183/Vvy3e2-1 Date: 08/06/2022  Code: AWA	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	XE 3039J	Veh. Inspected	JSL 2358
Policy No.	BVFCB0013382102	Coverage (\$)	0.00
Claim No.	NSV2100101/HLF	Excess (\$)	0.00
Assign From	Hew Lee Fong	Assign Date	20/04/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	YAMAHA R25	c.c	250
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	PMYRG1510H0011134	Colour	BLACK
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	100/80-17	PIRELLI	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	140/70-17	PIRELLI	6 mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	29/07/2021	Inspection Date	03/08/2021
Survey held at	EQUATOR BROTHERHOOD 25 KAKI BUKIT ROAD 4 #03-19 SYNERGY @KB SINGAPORE 417800		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	