

# MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

<b>TO</b>	: AIG	<b>DATE</b>	: 25-Apr-22
<b>ATTENTION</b>	: MOTOR CLAIMS DEPT	<b>JOB TYPE</b>	: T/P CLAIM
<b>ESTIMATE REPORT :</b>			
<b>VEHICLE DETAILS</b>			
<b>VEHICLE NO</b>	: GBH4565U		
<b>MODEL</b>	: NISSAN URVAN		JN, MC2E2620008657
<b>CHASSIS NO</b>			
<b>ACCIDENT DETAILS</b>		<b>DATE</b>	: 12-Apr-22
		<b>TIME</b>	: 12:55HRS
<b>THIRD PARTY REQUESTOR / CONTACT</b> : JACK LI			

## CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT SIDE MIRROR ASSY <i>Paint</i>	1	\$ 520.80	\$ 520.80
2	FRONT SIDE MIRROR COVER <i>Paint</i>	1	\$ 130.00	\$ 130.00
3	FRONT DOOR LH <i>New</i>	1	\$ 1,533.50	\$ 1,533.50
4	FRONT DOOR GLASS <i>cut</i>	1	\$ 520.80	\$ 520.80
5	SLIDING DOOR LH <i>Dented</i>	1	\$ 1,688.50	\$ 1,688.50
6	REAR SIDE DOOR RAILING LH <i>Dented</i>	1	\$ 345.60	\$ 345.60
7	REAR SIDE DOOR RAILING END LH <i>New</i>	1	\$ 56.80	\$ 56.80
8	TAIL LAMP LH <i>cut</i>	1	\$ 374.40	\$ 374.40
9	REAR SIDE PANEL LH <i>Dented</i>	1	\$ 2,855.30	\$ 2,855.30
10	REAR BUMPER <i>corn</i>	1	\$ 765.00	\$ 765.00
11	REAR BUMPER SIDE RETAINER <i>New</i>	1	\$ 80.00	\$ 80.00

5430.80

TOTAL PRICE \$ 8,870.70

4887.72

LESS 10% \$ 887.07

**SUB TOTAL PRICE \$ 7,983.63**

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT DOOR COMPANY STICKER <i>New</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER CLIPS(SET) <i>New</i>	1	\$ 20.00	\$ 20.00

20

TOTAL \$ 70.00

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT )**

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	600	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	800.	
3	WIRING CHECK	\$ 80.00	30.	
4	TO REMOVE AND REFFIX SLIDING DOOR MECHANISM	\$ 120.00	60	
5	TO REMOVE AND REFIX REAR REVERSE SENSOR	\$ 100.00	50.	

TOTAL \$ 3,300.00

1540

**ESTIMATE REPORT**

TOTAL PARTS COST : \$ 8,053.63  
 TOTAL LABOUR COS : \$ 3,300.00  
 TOTAL REPAIR COST : \$ 11,353.63

Adnan Lj  
 L/S 26/04/22 .  
 06 Days .

**APPROVED DETAILS**

EXCESS :  
 NO. OF WORKING DAYS :  
 RE-SURVEY :  
 PART BY PART OR LUMP SUM :  
 DATE & TIME OF SURVEY :  
 SURVEYED BY :  
 CONTACT NUMBER :  
 FAX NUMBER :

total: 6447.72  
 L/S: S.I.K ✓

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: