

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte.
Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Hor, Yinrul

Date: 19 May 2022

Preliminary Advice

Vehicle No	: SKC206C	Accident Date	: 14/04/2022
Make	: AUDI A5	Policy No.	: 1800093184
Assignment Date	: 21/04/2022	Excess	: S\$800.00
Date of Inspection	: 20/04/2022	Est. Duration of Repair	: 12
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 78,092.00	(Estimate \$77,502.00 + Supplementary \$590.00)
Revised Amount	:S\$ 47,134.50	(Inclusive of supplementary)
Check Items (Estimated)	:S\$ 12,707.00	
Total	:S\$ 59,841.50	
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 146,000.00
COE / PARF Rebate	:S\$ 55,998.00
Salvage Value	:S\$
Margin for Repair	:S\$ 90,002.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :