

## LKK AUTO CONSULTANTS PTE LTD

51 Ubi Ave1, #01-25 Paya Ubi Industrial Park, Singapore 408933.

TEL : 6256 3561

FAX : 6256 4315

Reg. No: 199607198R

GST Reg. No. 19-9607198-R

MINISTRY OF DEFENCE  
HQ-TRANSPORT COMMAND  
KRANJI CAMP 3  
151 CHOACHU KANG WAY  
SINGAPORE 688248

REF No. AC2300197DG  
REF Date 16/1/2023  
Code MIDA

### DISBURSEMENT FEE

IOD Number CY 22/MID21263/130422/0014  
PO Number OA22004224  
SAF Vehicle MID 21263  
Civillian Vehicle SLH 2415P  
Accident Date 13/04/2022  
Inspection Date 18/04/2022

| <b><u>LKK Cost of Claim paid to claimant on behalf of MINDEF</u></b> |                   |                   |                    |  |
|----------------------------------------------------------------------|-------------------|-------------------|--------------------|--|
|                                                                      | <b>Unit Price</b> | <b>GST Amount</b> | <b>Total</b>       |  |
| Repair Cost of SLH 2415P                                             | \$ 2,900.00       | N.A               | \$ 2,900.00        |  |
| Loss of Use (\$80 x 4day)                                            | \$ 320.00         | N.A               | \$ 320.00          |  |
| <b>Total Fee</b>                                                     |                   |                   | <b>\$ 3,220.00</b> |  |

We shall be glad if you could forward us the payment at your early convenience.

Cheque should be crossed and made payable to "LKK AUTO CONSULTANTS PTE LTD".

LKK AUTO CONSULTANTS PTE LTD

YUYU