

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305513213

Date 28.04.22

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax 6548 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr THEVAN

Vehicle Reg No. SHC8466B

Date of Accident : 20.04.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


1. The repair job shall bill to: TOKIO --- SJF8881X
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$1,864.04
 - (b) Labour Charges \$951.00
 - Total for Part-By-Part Repair Cost \$2,815.04**
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : JUMANI

Tel : 62148315

Fax : 65468156

Signature : _____

Name : THEVAN

Date : _____

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	NO		
3. Survey Fees	---	---		
LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 27.04.2022
Time: 14:08:51
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305513213
REGN NO : SHC8466B
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4A)
DATE OF REGN : 24.03.2022
DATE/TIME IN : 20.04.2022 16:00
ACCIDENT DATE : 21.04.2022

JOB / PARTS DESCRIPTION

QTY IND UNTT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2712-G	COVER REAR BUMPER#	1	503.04	25.00	377.28
0002 04-01-0302-2267-G	BUMPER PIECE	10	22.00	25.00	16.50
0003 04-01-0302-2713-G	GUARD REAR BUMPER CENTER	1	654.96	25.00	491.22
0004 04-01-0302-2715-G	COVER RR BUMPER -TOW HOOK	1	82.70	25.00	62.02
0005 04-01-0302-2719-G	LENS & BODY RR COMB RH LO	1	570.00	25.00	427.50
0006 04-01-0302-2725-G	RETAINER REAR BUMPER LH	1	94.80	25.00	71.10
0007 04-01-0302-2717-G	LENS & BODY RR RH UPPER	1	557.90	25.00	418.42

SUB-TOTAL : 1,864.04

LAB NATURE

0000 PB	PANEL BEAT (SHC8466B)TP	350.00
0001 SP	SPRAYPAINT CHARGE	500.00
0002 17-01	CHECK ALL LIGHTING	30.00
0003 20-00	TUFF COAT ON AFFECTED PARTS.	30.00

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 27.04.2022

Time: 14:08:51

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305513213
REGN NO : SHC8466B
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID
DATE OF REGN : 24.03.2022
DATE/TIME IN : 20.04.2022 16:0
ACCIDENT DATE : 21.04.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0004 L	REMOVE/REFIX REVERSE SENSOR	30.00
0005 L	MERIMEN FEE	11.00

SUB-TOTAL : 951.00

TOTAL : 2,815.04

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

4/21/22, 8:54 AM

ASSIGNMENT

Veh No:

Shu9140k

Yr Regn: 22/6118

Repairer Estimates

REPAIR DETAILS

Reference

Part Source: MRM-SG

Parts: 144

Labour: Repairer's

Print Code: ComfortDelGro Engineering Pte Ltd/SHC8466B/21/04/2022 08:53

Validity:

Version: 1.0 (Last Synchronised: 21 Apr 2022)
 TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
 (Price-denominated Standard List)
 These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER ASSY			*503.04 FL
2	10		*REAR BUMPER CLIPS	25.00	0.00	*22.00 FL
3	1		*REAR BUMPER CENTRE GUIDE	25.00	0.00	*654.96 FL
4	1		*REAR BUMPER TOW COVER	25.00	0.00	*82.70 FL
5	1		*REAR BUMPER REFLECTOR RH	25.00	0.00	*55.00 FL
6	1		*REAR BUMPER BEAM	25.00	0.00	*378.32 FL
7	1		*REAR BUMPER BRACKET RH	25.00	0.00	*94.80 FL
8	1		*TAILLAMP ASSY UPPER RH	25.00	0.00	*557.90 FL
9	1		*TAILLAMP ASSY LOWER RH	25.00	0.00	*570.00 FL

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$) 2,918.72

- List Item Discount on L Items (\$\$) 729.68

Total Parts (\$\$) 2,189.04

ComfortDelGro Engineering Pte Ltd/SHC8466B/21/04/2022 08:53. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

4/21/22, 8:54 AM

Date

Veh No:

Sm99140k

Yr Regn:

2216118

Repairer Estimates

Estimates on Miscellaneous Items

No Qty Particulars

Miscellaneous Items

No	Qty	Particulars	Amount
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No Particulars

Labour Items

No	Particulars	Lab.Type	Amount
1	PANEL BEATING	New	400.00
2	SPRAYPAINT	New	600.00
3	CHECK WIRING	New	50.00
4	TUFF KOTE	New	50.00
5	REMOVE/REFIX REVER SENSOR	New	50.00
Gross Labour Cost (S\$)			1,150.00

ComfortDelGro Engineering Pte Ltd/SHC8466B/21/04/2022 08:53. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Thuan

82235769

21/4/22 1615

17/11/2022 delay swp

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer