

CONFIRMATION / ESTIMATE COST OF REPAIRS

REG NO: SKM6318X <i>86116755 Rusdi</i>	MODEL : FORESTER 2.0I-L AWD CVT YEAR: 27 APRIL 2018
ENGINE NO: FB20YD31742	CHASSIS NO: JF1SJ5KC5JG107630
DATE IN:	CASH REPAIR ESTIMATE / QUOTATION

S/N	NATURE OF JOB		AMOUNT	
1.	TO RESPRAY WHOLE CAR		\$3700 ✓	
2.	TO INSTALL ALL MOULDINGS AND NECESSARY ITEMS		2740 \$1000 800 1600 ✓	
S/N	Total Labour			
S/N	PARTS DESCRIPTION	PRICE		
1.		QTY	LIST	S/NETT
2.	FRONT BUMPER / (Stained by paint)	1	\$610.50	8471.35 ✓
3.	FRONT SPORT GRILLE / "	1	\$600	490 ✓
4.	FRONT BUMPER UNDER SPOILER / "	1	\$699	481.30 ✓
5.	LAMP ASSEMBLY HEADLIGHT - RIGHT / "	1	\$2380	1666 ✓
6.	LAMP ASSEMBLY HEADLIGHT - LEFT / "	1	\$2380	1666 ✓
7.	DAM RUBBER-FRONT LOWER / n/c	1	\$14.80	70.72 ✓
8.	DAM RUBBER-FRONT UPPER / n/c	1	\$14.80	
9.	FRONT WINDOW MOULDING / n/c	1	\$111.00	77.70 ✓
10.	WEATHER STRIP-DOOR OUT RIGHT nec X n/c	1	\$103.60	72.52
11.	WEATHER STRIP-DOOR OUT RIGHT nec X n/c	1	\$103.60	72.52
12.	TAPE FRONT DOOR SASH RIGHT / "	1	\$18.50	17.95 ✓
13.	TAPE FRONT DOOR SASH LEFT / "	1	\$18.50	17.95 ✓
14.	TAPE REAR DOOR SASH RIGHT / "	1	\$18.50	17.95 ✓
15.	TAPE REAR DOOR SASH RIGHT / "	1	\$18.50	17.95 ✓
16.	TAPE FRONT DOOR SASH REAR RIGHT / "	1	\$18.50	17.95 ✓
17.	TAPE FRONT DOOR SASH REAR LEFT / "	1	\$18.50	17.95 ✓
18.	TAPE REAR DOOR SASH CENTRE RIGHT / "	1	\$11.10	7.77 ✓
19.	TAPE REAR DOOR SASH CENTRE LEFT / "	1	\$11.10	7.77 ✓
20.	TAPE REAR DOOR SASH REAR RIGHT / "	1	\$14.80	10.36 ✓
21.	TAPE REAR DOOR SASH REAR LEFT / "	1	\$14.80	10.36 ✓
22.	TAPE FRONT DOOR RIGHT / "	1 5.55	\$5.60	3.89 ✓
23.	TAPE FRONT DOOR LEFT / "	1 5.55	\$5.60	3.89 ✓
24.	RUN CHANNEL FRONT DOOR RIGHT / "	1	\$74.00	51.80 ✓
25.	RUN CHANNEL FRONT DOOR LEFT / "	1	\$74.00	51.80 ✓
26.	RUN CHANNEL REAR DOOR RIGHT / "	1	\$74.00	51.80 ✓
27.	RUN CHANNEL REAR DOOR LEFT / "	1	\$74.00	51.80 ✓
28.	WEATHER STRIP DOOR REAR OUTER RIGHT / "	1	\$103.60	77.57 ✓
29.	WEATHER STRIP DOOR REAR OUTER LEFT / "	1	\$103.60	77.57 ✓
30.	RUBBER REAR GATE X n/c nec	1	\$13.00	9.07
31.	DAM RUBBER REAR GATE GLASS / n/c	2	\$7.40	5.18 ✓
32.	MUD GUARD REAR RIGHT X n/c	1	\$59.20	
33.	MUD GUARD REAR LEFT X n/c	1	\$59.20	
34.	REAR BUMPER UNDER SPOILER / "	1	\$851.00	595.70 ✓

35.	LENS & BODY REAR COMBINATION LAMP RIGHT ✓	"	1	\$444.00	310.80/
36.	LENS & BODY REAR COMBINATION LAMP LEFT ✓	"	1	\$444.00	310.80/
37.	GARNISH ASSEMBLY REAR GATE X	h/n	1	\$148.00	
38.	PROTECTOR REAR GARNISH X	-H- nec	1	\$22.20	15.54
39.	PROTECTOR REAR GARNISH X	-H- nec	2	\$11.20	7.78
40.	ORNAMENT	PC	1	\$81.40	56.98/
41.	LETTER MARK REAR (NO-STOCK)	PC	1	\$40.70	98.44/
42.	LETTER MARK REAR	PC	1	\$66.60	46.62/
43.	LETTER MARK R SPORT	PC	1	\$74.00	51.80/
44.	ARM ASSEMBLY WINDSHIELD WIPER DRIVER ✓	"	1	\$61.20	47.84/
45.	ARM ASSEMBLY WINDSHIELD WIPER ASSISTOR ✓	"	1	\$61.20	47.84/
46.	BLADE ASSEMBLY WINDSHIELD WIPER DRIVER ✓	"	1	\$59.20	33.67/
47.	BLADE ASSEMBLY WINDSHIELD WIPER ASSISTOR ✓	"	1	\$48.10	33.67/
48.	ARM ASSEMBLY REAR WIPER	"	1	\$44.40	47.84/
49.	BLADE ASSEMBLY REAR WIPER	"	1	\$25.90	18.13/
50.	ROOF RAIL ASSEMBLY RIGHT ✓	"	1	\$444.00	310.80/
51.	ROOF RAIL ASSEMBLY LEFT ✓	"	1	\$444.00	310.80/
52.	MOULDING ROOF RIGHT ✓	"	1	\$74.00	51.80/
53.	MOULDING ROOF LEFT ✓	"	1	\$74.00	51.80/
54.	REAR BUMPER CARGO STEP PANEL S/S ✓	"	1	\$230.00	161/
SUB TOTAL:					161/
-					
LABOUR TOTAL				\$4700	
PARTS TOTAL				\$11563.90	
TOTAL				\$16263.90	
GST 7%				\$1138.48	
GRAND TOTAL				\$17402.38	

DATE APPROVAL:	
TIME APPROVAL:	
CONTACT PERSON:	MUHAMAMD RUSYDI
DID / EMAIL / HP:	86116758 – MUHAMMADRUSYDI@MOTORIMAGE.NET

REPAIR DAYS REQUIRED: 15-16 WORKING DAYS

**** Please also be informed that the attached is an estimate based on our physical inspection and does not cover any additional parts or labour which may be required after the work has been opened up. Occasionally after the work has started, damaged or broken parts are discovered which are not evident on the first inspection. ****

Steve (LKK)
6/5/22, 2.3pm
8322 8813

00-1111
EX-1
P/P
L/M/L
15 d/s

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: