



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD
C/O TOPLIS AND HARDING (S) PTE LTD
133 CECIL STREET
#17-01A
KECK SENG TOWER
SINGAPORE 069535

Ref: CS/TPS22003706/Evy3

Date: 21/04/2022

Code: CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SKM 6318X
Policy No.	Y226205	Coverage (\$)	0.00
Claim No.	SNC22D200008	Excess (\$)	0.00
Assign From	VICTOR FONG	Assign Date	21/04/2022

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	21/03/2022	Inspection Date	06/05/2022
Survey held at	25 LENG KEE ROAD SINGAPORE 159097		
Repairer	MOTOR IMAGE ENTERPRISES PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--