

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	TOPLIS AND HAR	DING (S) PTE LTD	R	ef:	CS/TPS22003710/y3	
	133 CECIL STREE #17-01A		D	ate:	21/04/2022	
	KECK SENG TOW	ER SINGAPORE 069535	C	ode:	TPS	
1.		- THIRD PARTY C				
1.	Insured Veh.	PUBLIC LIABILITY	Veh. Inspected		SKV 8325P	
	Policy No.	- ODEIO EI/ABIEIT I	Coverage (\$)		0.00	
	Claim No.	SNC22D200008	Excess (\$)		0.00	
	Assign From	VICTOR FONG	Assign Date		21/04/2022	
0	Assign From				21/04/2022	
2. Vehicle Particulars & Condition						
	Make & Model	LUDDEN	C.C		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.	Colour				
	Odometer	Steering				
	Brakes	Modification				
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	General Information					
	Accident Date	21/03/2022	Inspection Date			
	Survey held at	PERFORMANCE MOTORS LTD				
		303 ALEXANDRA ROAD SINGAPORE 159941				
5a. Remarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					