

Shiau Chan (LKKAUTO)

From: Simon Ho (LKKAUTO)
Sent: Friday, 29 April 2022 4:31 PM
To: Shiau Chan (LKKAUTO)
Subject: Re: TOPLIS-TP SKV 8325P SURVEYED BY STEVE (OUR REF: CS/TPS22003710/Eqy3)

Dear Shiau Chan,

Audit check done for SKV8325P without problem.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Friday, 29 April 2022 4:24 pm
To: Simon Ho (LKKAUTO) <SimonHo@lkkauto.com>
Subject: RE: TOPLIS-TP SKV 8325P SURVEYED BY STEVE (OUR REF: CS/TPS22003710/Eqy3)

Dear Simon,

For your re-audit. SKD 5157Y also have re-adjusted the repair cost and estimate.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Simon Ho (LKKAUTO) <SimonHo@lkkauto.com>
Sent: Friday, 29 April 2022 2:05 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: Re: TOPLIS-TP SKV 8325P SURVEYED BY STEVE (OUR REF: CS/TPS22003710/Eqy3)

Dear Shiau Chan,

AUDIT CHECK DONE FOR SKV8325P, FOUND ANOTHER SIMILAR CAR SKD5157Y MAIN PB & SP LABOUR DIFFERENT THAN THIS CAR.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>

Sent: Friday, 29 April 2022 1:16 pm

To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>

Subject: RE: TOPLIS-TP SKV 8325P SURVEYED BY STEVE (OUR REF: CS/TPS22003710/Eqy3)

Dear Simon,

For your audit. Steve had re-adjust the repair cost.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>

Sent: Wednesday, 27 April 2022 5:30 PM

To: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>

Subject: Re: TOPLIS-TP SKV 8325P SURVEYED BY STEVE (OUR REF: CS/TPS22003710/Eqy3)

Dear Shiau Chan,

Audit check done for SKV8325P without problem.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>

Sent: Wednesday, 27 April 2022 3:49 pm

To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>

Subject: TOPLIS-TP SKV 8325P SURVEYED BY STEVE (OUR REF: CS/TPS22003710/Eqy3)

Dear Simon,

For your audit.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)