

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



supplementary

Estimate No. : **b1 61319**
Date Estimated : **30/03/2022**
Prepared By : **Chua Kee Sin**

- ESTIMATE REPAIR FOR -
Scharenguivel Royston George Jr
Blk 53 Chai Chee Street
#13-336

Singapore 460053

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKV8325P	WBA2X92090VD113	28/08/2018	216i Active Tourer	34682

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

# To replace rear left and right window fixed glass.	676.00	0.00	676.00 ✓
# To replace both front Quarter glass for left and right.	676.00	0.00	676.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# 3M S/F PLATINUM FRONT WINDSCREEN	308.41	1.00	0.00	308.41 ✓
# LH MIRROR TRIANGLE OUTER SEAL	29.70	1.00	0.00	29.70 ✓
# LH COVER COLUMN A (OYSTER)	58.35	1.00	0.00	58.35 ✓

SUPPLEMENTARY ITEMS

Total Labour :	1,352.00
Total Parts :	396.46