



TRANS EUROKARS PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
FINALIZE COST OF REPAIRS



SBS TRANSIT 205 BRADDELL ROAD SINGAPORE 579701		NAME : ADDRESS : TEL :		WIP : 22462 EXCESS : DATE: 25-May-22	
ATTN : MOTOR CLAIMS					
FAX :					

VEH NO :	SLB5621Y	DATE IN :		CONTACT PERSON :	JESS
CHASSIS NO :	JM6BM42A8G0338564	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA 3	DATE REG.:	13-Apr-16	POLICY NO. :	

NATURE OF WORKS								
NO	DESCRIPTION	QTY	UNIT PRICE	1st	Supp	PARTS NO	REVISED	PRICES
1	REAR BUMPER	1	1,047.30	✓		MBPD8-50-221ABB	1,047.30	1,047.30
2	BRACKET CENTER REAR BUMPER	1	5.40	✓		MDFR5-50-251	5.40	5.40
3	REINFORCEMENT REAR	1	564.20		✓	MB45A-50-260	564.20	564.20
4	TAPE PROTECTOR	3	8.60	✓		MGS1D-50-EM1A	25.80	25.80
5	RETAINER S.S ULTRASONIC CENTER	2	18.20	✓		MKD47-67-UC5A13	36.40	36.40
6	SENSOR,ULTRASONIC CENTER	2	203.60	✓		MKD47-67-UC1 13	407.20	407.20
7	RIVET	4	4.50	✓		MBBM4-50-355	18.00	18.00
8	GROMMET,SCREW	4	2.70	✓		MBHN1-50-0Z1A	10.80	10.80
9	CLIP	2	3.40	✓		MGJ21-50-049	6.80	6.80
10	FASTENER	4	3.00	✓		MB45A-56-146A	12.00	12.00
11	TRUNK LID	1	1,005.30	✓		MBHY2-52-61XB	1,005.30	1,005.30
12	SWITCH OPEN TRK LID	1	109.20			MBHN1-56-8D0B		109.20
13	CAMERA-BACK MONITOR	1	755.40			MBHN1-67-RC0A		755.40
14	GASKET RH LAMP TRUNK LID	1	22.00	✓		MB45A-51-3H8	22.00	22.00
15	GASKET LH LAMP TRUNK LID	1	22.00	✓		MB45A-51-3J8	22.00	22.00
16	FASTENER	2	6.20	✓		MEG21-51-146	12.40	12.40
17	GROMMET,SCREW-R.COMB	2	3.30	✓		MGA7B-51-146	6.60	6.60
18	GASKET RH TAIL LAMP	1	22.00	✓		MBHN1-51-153	22.00	22.00
19	GASKET LH TAIL LAMP	1	22.00	✓		MBHN1-51-163	22.00	22.00
20	ORNAMENT MAZDA 3	1	56.10	✓		MBHN1-51-721	56.10	56.10
21	ORNAMENT SKYACTIVE	1	66.80	✓		MBHN1-51-771	66.80	66.80
22	MASCOT REAR	1	78.20	✓		MBHN1-51-730	78.20	78.20

SUPPLEMENTARY								
NO	DESCRIPTION	QTY	UNIT PRICE	1st	Supp	PARTS NO	REVISED	PRICES
1	REAR END PANEL DD	1	530.40		✓	MB4YA-70-75Z	530.40	
						TOTAL PARTS	3,977.70	4,311.90
						TOTAL PARTS COST	3,977.70	4,311.90

Labour Description