

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

AJS AUTO LEASING PTE LTD
10 ANSON ROAD #10-11 INTERNATIONAL
PLAZA
SINGAPORE 079903

Contact : 91166658, 83362468

TP China.
Xiao Chan.

TAX INVOICE

Repair Code : CLM17160

Date in : 15/04/2022

Vehicle Num. : GBK4426Y

Model : NISSAN NV200 VANETTE DX 1.6 AUTO

Chassis/Eng# : VM20157135/HR16169257D

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>lot</i>	1	485.90	✓ 485.90
REAR BUMPER SIDE RETAINER L/R <i>men</i>	2	37.20	+ 74.40
REAR RH ARCH PANEL <i>Rejis</i>	1	1353.60	+ 1,353.60
REAR RH TAILLAMP <i>lot</i>	1	258.00	✓ 258.00
REAR RH WHEEL BEARING HUB <i>Revised</i>	1	346.60	✓ 346.60
REAR SLIDING DOOR <i>Deted</i>	1	1229.00	✓ 1,229.00
REAR SLIDING DOOR INNER PLASTIC SEAL COVER <i>men</i>	1	35.00	+ 35.00
Subtotal before discount			3,782.50
Percentage discount 10%			378.25
Sub-total 1			3,404.25
REAR BUMPER CLIPS - SET <i>men</i>	1	50.00	30 50.00
REAR RH TAILLAMP CLIPS - SET <i>men</i>	1	30.00	10 30.00
REAR RH TYRE <i>men</i>	1	250.00	+ 250.00
REAR RH WHEEL RIM <i>lot</i>	1	207.20	✓ 207.20
REAR SLIDING DOOR 3D ART WORK STICKER <i>men</i>	1	280.00	180 280.00
REAR SLIDING DOOR GLASS SEALANT <i>men</i>	1	80.00	40 80.00
REAR SLIDING DOOR INNER TRIM BOARD CLIPS - SET <i>men</i>	1	50.00	+ 50.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

AJS AUTO LEASING PTE LTD
10 ANSON ROAD #10-11 INTERNATIONAL
PLAZA
SINGAPORE 079903

Contact : 91166658, 83362468

TAX INVOICE

Repair Code : CLM17160

Date in : 15/04/2022

Vehicle Num. : GBK4426Y

Model : NISSAN NV200 VANETTE DX 1.6 AUTO

Chassis/Eng# : VM20157135/HR16169257D

Subtotal before discount	947.20
Percentage discount 0%	0.00
Sub-total 2	947.20
Parts-total	4,351.45

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall window glass. (to FR)

To remove, reinstall rear suspension and undercarriage part. (to FR)

To road test driving, check and resetting wheel alignments system.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

814 60.00 60
x 120.00
80 150.00
100.00 80
x 120.00
60 100.00
500 1,000.00
500 900.00
60 80.00

1340

2,630.00

6,981.45

Alan L
4/s 25/04/22.

*** This is a computer-generated document which requires no signature.***

page 2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

04 Days
total: 388475
4/s: 3.1K
3.1K