CONNECTS

566 Woodlands Road (Mandai Estate) Singapore 728697 Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

ROC:53360061L GST:53360061L

QT22/PC3249A/TPC

China Taiping Insurance (Singapore) Pte Ltd	
3 Anson Rd #15-02	
Springleaf Tower	
Singapore 079909	

QUOTATION

Dear Sir,

Cost of Repair to Vehicle PC3249A

With reference to the above-mentioned, we are pleased to quote as follows:-

	No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
P.	1.	Front RH rear view mirror assy / JR	1	1,630.00	1,630.00
-	2.	Check wiring	1	40.00 30	40.00
	3.	Labour charges	1	300.00	300.00
	4.	Spray painting	1	300.00 290	300.00
		P-Blind spd mirror \$117 / BR (SN)		SUB-TOTAL	S\$2,270.00

2383.00

Price before 7% gst

Thank you.

Yours faithfully,

Winnie Chai

HP: 9850-9666

Steve (LKK) 92/4/92, 19-90

MAPIP MMM 2 dys 113 - 10% 1580 † 430 2010