

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS4/CTI22003776/NNY3E2**Date:** 06/10/2022**REFERENCE**

Insured/Claimant: KONTOURZ PTE LTD Policy No: DMCVSNA00118172102
Date of Loss: 20/04/2022 Nature of Claim: OD Claim No: SNM22D202713/C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBC3173A**
Make & Model: NISSAN NV200, 1.5 L (M) Engine No: K9KF276D124523
Reg. Date: 22/11/2011 (Man. Year: 2011) Chassis No: VSKYBAM20U0026614
Colour: Grey Odometer: 0 km
Engine Capacity: 1461 cc
Market Value/New Car Price: S\$58,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14
Front Left Side: Arivo 7 mm Rear Left Side: Arivo 3 mm
Front Right Side: Arivo 7 mm Rear Right Side: Arivo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
- Excess (S\$)	600.00	600.00	0.00	0.00
Nett Amount (S\$)	-600.00	-600.00	0.00	0.00

INSPECTION

Date of Assignment: 25/04/2022

Date Inspected: 25/04/2022 Inspected At:

Hup Soon Lee Motor Service (HQ)
Blk 1018 Yishun Industrial Park A, 01-352
Singapore 768760

Estimated Period of Repair: 0.0 days

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$58,000.00
OMV :	\$21,778.00
PARF Rebate (1) :	\$0.00
Quota Premium Paid :	\$40,166.00
COE Rebate (2) :	\$38,435.00
Total Rebate (1) + (2) = :	\$38,435.00

The total amount incurred will be Market Value \$58,000.00 minus Total Rebate \$38,435.00 = \$19,565.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 06 Oct 2022)	
Parts:	N/A	NISSAN NV200 1.5 L (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC3173A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >