



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: TEO KITTY			Ref: CS/ASM22003783/Gny3e2 Date: 07/07/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YN 6743E	Veh. Inspected	SKC 4752R
	Policy No.	GA504832/1	Coverage (\$)	0.00
	Claim No.	S2M03Z7I	Excess (\$)	0.00
	Assign From	TEO KITTY	Assign Date	25/04/2022
2. Vehicle Particulars & Condition				
	Make & Model	VOLKSWAGEN TOURAN 1.4L	c.c	1390
	Engine No.	HIDDEN	Year of Reg.	2011
	Chassis No.	WVGZZZ1TZCW006405	Colour	BLUE
	Odometer	121023 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	DUNLOP	6 mm
	L/H Front Tyre	205/60 R16	DUNLOP	6 mm
	R/H Rear Tyre	205/60 R16	DUNLOP	6 mm
	L/H Rear Tyre	205/60 R16	DUNLOP	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	20/04/2022	Inspection Date	25/04/2022
	Survey held at	SPEEDWERKZ PTE LTD 13 KAKI BUKIT ROAD 4, #01-20, BARTLEY BIZ CENTRE, SINGAPORE 417807		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	