



DICKSON GROUP
Your Trusted Automotive Solutionist

DICKSON AUTO CARE CENTRE PTE LTD
29 UBI ROAD 4, DICKSON AUTO CENTRE
SINGAPORE 408619
TEL: 6668 1122 | FAX: 6668 1123

QUOTATION

QUOTATION FOR

DATE: 22/4/2022

NAME: China Taiping Insurance (Singapore) Pte. Ltd
COMPANY NAME: China Taiping Insurance (Singapore) Pte. Ltd
STREET ADDRESS: 3 Anson Road, #16-00 Springleaf Tower
POSTAL CODE: Singapore 079909
PHONE: 6389 6111

REF: SMR3913J
VEHICLE NO.: SMR3913J
MAKE: MAZDA
MODEL: 5
PREPARED BY: POON

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
LABOUR							
1	TO REMOVE & REPLACE REVERSE SENSOR AND WIRING	1		\$200.00	\$ 200.00		\$ 200.00
2	TO PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS & PANELS, CUT & WELD IN PLACE NEW PARTS & PANELS WITH FULL ALIGNMENT	1		\$800.00	\$ 800.00		\$ 800.00
3	TO PROVIDE SKILL LABOUR & MATERIAL TO PREPARE & PAINT ALL NEW PARTS & PANELS	1		\$800.00	\$ 800.00		\$ 800.00
PARTS							
1	TAIL GATE	1		\$1,638.00	\$ 1,638.00		\$ 1,638.00
2	TAIL GATE LOGO	1		\$45.00	\$ 45.00		\$ 45.00
3	TAIL GATE MAZDA LOGO	1		\$46.00	\$ 46.00		\$ 46.00
4	TAIL GATE 5 LOGO	1		\$37.00	\$ 37.00		\$ 37.00
5	TAIL GATE SKYACTIVE LOGO	1		\$80.00	\$ 80.00		\$ 80.00
6	REAR BUMPER	1		\$962.00	\$ 962.00		\$ 962.00
7	REAR BUMPER CLIPS	10		\$10.00	\$ 100.00		\$ 100.00
8	REAR BUMPER SIDE RETAINER LH & RH	2		\$48.00	\$ 96.00		\$ 96.00
9	REAR BUMPER REINFORCEMENT	1		\$156.00	\$ 156.00		\$ 156.00
10	REAR END PANEL	1		\$516.00	\$ 516.00		\$ 516.00
11	REVERSE SENSOR	1		\$250.00	\$ 250.00		\$ 250.00
SUBTOTAL					\$ 5,726.00	SUBTOTAL	\$ 5,726.00
GST 7%					\$ 400.82	GST 7%	400.82
TOTAL					\$ 6,126.82	TOTAL	\$ 6,126.82

REMARKS: PLEASE TAKE NOTE IT MAY HAVE ADDITIONAL ITEM TO ADD ON AFTER REMOVE.

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD

(CUSTOMER'S SIGNATURE AND
COMPANY STAMP)

(AUTHORISED SIGNATURE)

