

SERVICE ESTIMATE

76996 - C00001 SL: SERVICE SALES - PC

Klenco (Singapore) Pte Ltd

Attn: Mr Peter Beh

18 Gul Crescent

Singapore 629527

Closed by : Juan Paulo Bongon Ba

Svc Consultant :

Remarks : Klenco (Singapore) P

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 22/04/2022

WIP No. . : 22136

Veh.In/Out:

*Tel.No. . : Mobile: 96260071

Reg.No. . : SBW71A

Reg.date . : 27/03/2014

Mileage ... : 0

Chassis No: JN1BCAY51Z0450026

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, REINFO	0		1200.00	0		1,200.00	S
	SENSOR, ETC							
800	TO SPRAY REAR BUMPER,	0		1800.00	0		1,800.00	S
	REINFORCEMENT, ETC							
280	TO CHECK WIRING INCLUDE	0		498.00	0		498.00	S
	RESETTING OF ALL ELECTRICAL							
	MODULES							
	REAR BUMPER M37 M25	1.0	EA	2269.40			2,269.40	S
	CLIP BUMPER REAR	15.0	EA	5.00			75.00	S
	REAR BUMPER FOAM	1.0	EA	417.50			417.50	S
	BRACKET BUMPER LH	1.0	EA	70.20			70.20	S
	BRACKET BUMPER RH	1.0	EA	70.20			70.20	S
	BUMPER BEAM REAR	1.0	EA	1489.00			1,489.00	S
	DIFFUSER ASSY	1.0	EA	101.80			101.80	S
	SENSOR-SCANNER	4.0	EA	289.00			1,156.00	S

Gross Total. 9,147.10

Labour Total 3,498.00
 Parts Total 5,649.10
 Package Total 0.00

Net..... 9,147.10
 GST @ 7.0% 640.30
 Total..... 9,787.40
 Paid..... 0.00
 Please Pay.. 9,787.40

GST: S=StdRated; O=OutOfScope; Z=ZeroRated