

not Authend

*Lee
Meyang*

27/4/22

*4/5 @ 1700
4 days*

ESTIMATE

Our Ref: AC2022025/TP

Vehicle number: SLM6914M

Vehicle Made & Model: TOYOTA WISH

Qty	List Items	Amount \$
1	1 TAILGATE	1340.00 X
2	1 TAILGATE LOGO	73.00 X
3	2 TAILGATE LAMP	596.00 X
4	2 TAILGATE NUMBER PLATE LAMP	124.00 X
5	1 TAILGATE OUTER MOULDING	290.00 X
6	1 TAILGATE OUTER LOCK BOTTOM	210.00 X
7	1 TAILGATE INNER LOCK	398.00 X
8	1 TAILGATE LOCK CATCH	35.00 X
9	1 TAILGATE WEATHER STRIP	320.00 X
10	1 TAILGATE INNER BOARD	450.00 X
11	2 TAILGATE DAMPER	392.00 X
12	1 TAILGATE DETECTOR	395.00 X
13	1 TAILGATE WIPER MOTOR	720.00 X
14	1 TAILGATE WIPER MOTOR HEAD COVER	42.00 X
15	1 TAILGATE WINDSCREEN MOULDING	140.00 X
16	1 REAR BUMPER	580.00 ✓
17	2 REAR BUMPER REFLECTOR	136.00 X
18	2 REAR BUMPER SIDE RETAINER	190.00 X
19	2 REAR BUMPER BRACKET	210.00 X
20	2 REAR FENDER INNER COWLING	760.00 X
21	2 REAR FENDER INNER TRIM	1660.00 X
22	1 REAR END PANEL	495.00 X
23	1 REAR END PANEL TOP GARNISH	295.00 X
24	1 REAR FLOOR PANEL TOP BOARD	598.00 X
25	1 REAR FLOOR PANEL SIDE BOARD RH	125.00 X
26	1 REAR FLOOR PANEL TOP INNER SUPPORT	498.00 X
Sub-total		11,072.00
Less 25%		2,768.00
Total List		8304.00

Vehicle number: SLM6914M

Vehicle Made & Model: TOYOTA WISH

Special Nett Items

1	REAR NUMBER PLATE	11	50.00	X
1	REAR BUMPER CLIPS (SET)	11	60.00	50
1	TAILGATE INNER BOARD CLIP (SET)	11	60.00	X
1	TAILGATE WINDSCREEN SEALANT	11	80.00	X
1	TAILGATE WINDSCREEN INNER SHIELD	11	60.00	X
1	TAILGATE EMBLEM 'VALVE MATIC' (SPECIAL TYPE)	11	120.00	60
1	REAR FENDER INNER COWLING CLIP (SET)	11	60.00	X
1	REAR FENDER INNER TRIM CLIP (SET)	11	60.00	X
1	REAR END PANEL INSULATION SEAL	11	150.00	X
1	REAR END PANEL TOP GARNISH CLIP (SET)	11	50.00	X
1	REAR MOULDING (SPECIAL TYPE) (SET)	11	120.00	X
1	REVERSE SENSOR	should	220.00	200
1	REVERSE CAMERA	11	450.00	X
Total Special Nett			<u>1,540.00</u>	

Labour charges

TO PANEL BEAT, REMOVE AND REPLACE PARTS	600	1600.00
TO SPRAY PAINT AFFECTED AREA	600	1600.00
TUFF COAT	11 X	250.00
WIRING AND BULB CHECK	20	180.00
REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING T	80	350.00
REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	50	80.00
CONDUCT WATER LEAKAGE TEST	11 X	80.00
REMOVE AND REFIX REVERSE CAMERA	11 X	120.00
REMOVE AND REFIX TAILGATE WINDSCREEN	11 X	80.00
REMOVE AND REFIX TAILGATE WINDSCREEN	Repair	120.00
TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL	11 X	180.00
UNITS, RESET MEMORIES TO SPECIFICATION ETC.		
Total Labour		<u>4,640.00</u>

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 14,484.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2 675
25X
50625
310