

# SDX 8188R

PARTS				S/N		LABOUR	SUPP (PARTS)		
	\$591.60				\$156.60		\$110.00		\$0.00
	\$0.00				\$103.90		\$250.00		\$0.00
	\$0.00				\$103.90		\$200.00		\$0.00
	\$0.00				\$0.00		\$0.00		\$0.00
	\$591.60				\$0.00		\$0.00		\$0.00
	80%				\$0.00		\$0.00		\$0.00
	\$473.28				\$0.00		\$0.00		\$0.00
					\$0.00		\$0.00		\$0.00
					\$0.00		\$0.00		\$0.00
					\$0.00		\$0.00		0%
					\$0.00		\$0.00		\$0.00
					\$0.00		\$0.00	SUPP (SN)	
					\$0.00		\$0.00		\$0.00
					\$0.00		\$0.00		\$0.00
					\$0.00		\$560.00		\$0.00
					\$0.00		95%		\$0.00
					\$0.00		\$532.00		\$0.00
					\$0.00				
					\$0.00			SUPP(LABOUR)	
					\$0.00	TOTAL			\$0.00
					\$0.00		\$449.62		\$0.00
					\$0.00		\$364.40		\$0.00
					\$0.00		\$532.00		\$0.00
					\$364.40	SUPP	\$0.00	TOTAL SUPP \$0.00	
						P/P	\$1,346.02	MAKE / MODEL	HYUNDAI I40 - 1685cc
						\$0.00	MARKET VALUE	\$0.00	
						0%	LTA REBATE	\$0.00	
						\$0.00	NETT VALUE	\$0.00	
						L/S	\$0.00	RED	\$1,549.66
			\$473.28			TOTAL TP EST		\$2,895.68	
			95%			REPAIR DAYS		3	
			\$449.62			REMARKS			