



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI22003896/Avy3e2 Date: 14/07/2022  Code: AGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SLN 2979Y	Veh. Inspected	SJV 1210U
Policy No.		Coverage (\$)	0.00
Claim No.	C10014870/JM	Excess (\$)	0.00
Assign From	SHAFAWATI MD RABU	Assign Date	26/04/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA VIOS	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	MR053HY9305133533	Colour	GOLD
Odometer	152716 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	185/60 R15	MICHELIN	6 mm
L/H Front Tyre	185/60 R15	MICHELIN	6 mm
R/H Rear Tyre	185/60 R15	MICHELIN	6 mm
L/H Rear Tyre	185/60 R15	MICHELIN	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	21/04/2022	Inspection Date	25/04/2022
Survey held at	1ST AUTOWORKS PTE LTD 23 KAKI BUKIT AVE 4 #04-01 (SOUNTH WING) SINGAPORE 415933		
<b>5a. Remarks</b>			
A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	