



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY 3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190			Ref: CS/GAI22003897/Eqy3e2 Date: 11/05/2022 Code: GAI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	CB 7550L	Veh. Inspected	SHC 7855T	
Policy No.		Coverage (\$)	0.00	
Claim No.	CLMOMVC000004156-50114128	Excess (\$)	0.00	
Assign From	SHERY WONG	Assign Date	26/04/2022	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI IONIQ	c.c	1580	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	KMHC851CVLU183592	Colour	YELLOW	
Odometer	251628 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	GOODYEAR	5 mm	
L/H Front Tyre	195/55 R15	GOODYEAR	5 mm	
R/H Rear Tyre	195/55 R15	GOODYEAR	5 mm	
L/H Rear Tyre	195/55 R15	GOODYEAR	5 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	26/04/2022	Inspection Date	26/04/2022	
Survey held at	31 Corporation Rd			
Repairer	DING AUTOMOTIVE PTE LTD			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	