



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22003905/Evy3e2 Date: 31/05/2022 Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHF 396G	Veh. Inspected	SHA 8278M	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/04/22/2073	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	26/04/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HYUNDAI I40	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KMHLB41UMHU097125	Colour	YELLOW	
Odometer	878666 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	SAILUN	4 mm	
L/H Front Tyre	205/60 R16	SAILUN	4 mm	
R/H Rear Tyre	205/60 R16	SAILUN	4 mm	
L/H Rear Tyre	205/60 R16	SAILUN	4 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	25/04/2022	Inspection Date	26/04/2022	
Survey held at	DING AUTOMOTIVE PTE LTD 10 SECTOR C SIN MING INDUSTRIAL EST, #01-20, SINGAPORE 575645			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			20 Working Days	