



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS3/SMR22002508/Gty3-1

STRIDES AUTOMOTIVE SERVICES PTE LTD

60 WOODLANDS INDUSTRIAL PARK  
E4SINGAPORE 757705

Ref: ~~CS3/SMR22002508/13~~

Date: ~~17/03/2022~~ 26/04/2022

Code: SMR

## 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SHD 6335D	Veh. Inspected	JSN 7092
Policy No.		Coverage (\$)	0.00
Claim No.	TAX/03/22/2031	Excess (\$)	0.00
Assign From	<del>HUIA YEN</del> JOEY	Assign Date	<del>17/03/2022</del> 26/04/2022

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--	--

## 5. General Information

Accident Date	10/03/2022	Inspection Date	18/03/2022
Survey held at	SIN SENG HONG SPRAY PAINTING & SERVICES BLK 3022A UBI ROAD 1 #01-53 . SINGAPORE 408716		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.