

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	STRIDES AUTOM	OTIVE SERVICES PTE LTD		Ref:	CS3/SMR22002508/Gty3n2-1	
	60 WOODLANDS E4SINGAPORE 75	INDUSTRIAL PARK 57705		Date:	12/05/2022	
				Code:	SMR	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHD 6335D	Veh. Inspected	k	JSN 7092	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	TAX/03/22/2031	Excess (\$)		0.00	
	Assign From	JOEY	Assign Date		26/04/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	YAMAHA Y15ZR	c.c		150	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	PMYUG0510J0129230	Colour		BLUE	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	80/90 R17	MAXXIS		4 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	110/70-17	METZELER		4 mm	
	L/H Rear Tyre				mm	
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	10/03/2022	Inspection Date	te	18/03/2022	
	Survey held at	SIN SENG HONG SPRAY PAIN	TING & SERVICE	S		
		3023A UBI ROAD 1 #01-53				
		SINGAPORE 408717				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					