

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
 Tel : 6366 2323 Fax : 6841 1183
 Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg




Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315	Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0326/2022/JT 18-May-22 CHANG 1 of 1 SDY 886 G AUDI Q2 1.0 TFSI
----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------

Quantity	Description	Unit Price	Amount
Labours			
1	TO REPAIR RHS B-PILLAR.	\$ 800.00	250
2	TO RESPRAY RHS B-PILLAR.	\$ 1,200.00	500
GRAND TOTAL		\$ 2,000.00	

For Premium Automobiles Pte Ltd



Authorized Signature

Steve (LKK)

18/5/22

add 1 day



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SDY 886 G

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER RHS FRONT AND REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES AND RHS FRONT WING MIRROR ASSY.	S/N \$ 640.00	560
2	TO DISMANTLE AND RENEW RHS FRONT AND REAR DOORS. INSPECT B-PILLAR FOR DAMAGES. REPAIR RHS REAR FENDER. REINSTALL ALL PARTS REMOVED.	\$ 2,800.00	1000 + 250 ✓
3	TO RESPRAY RHS FRONT AND REAR DOOR AND REAR RHS REAR FENDER.	\$ 2,700.00	1800 2 x 550 = 1650 Mirror = 150 <u>1800</u>
4	TO RENEW RHS FRONT TYRE. CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	✗
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>6,612.00</u>	

Carin 12/5/22

wip: 21091

Benzi

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ATG - Adrian
- 5 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDY 886 G - FRONT

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT DOOR - RH Distorted	1	\$	2,962.00	✓
2	GROMMET New	6	\$	15.00	✓
3	FRONT DOOR CATCH - RH ?	1	\$	134.00	?
4	FRONT DOOR ATTACHMENT PARTS New	1	\$	98.00	x
5	FRONT DOOR HANDLE - RH Cut	1	\$	398.00	✓
6	FRONT DOOR SLIDE VALVE - RH New	1	\$	25.00	x
7	FRONT DOOR HANDLE SENSOR - RH New	1	\$	255.00	x
8	FRONT DOOR HANDLE CAP - RH Not New	1	\$	62.00	x
9	FRONT DOOR UNDERLAY - RH ?	1	\$	6.00	+
10	FRONT DOOR UNDERLAY END - RH } New	1	\$	7.00	+
11	FRONT DOOR MOUNTING BAR - RH	1	\$	178.00	x
12	FRONT DOOR WINDOW APERTURE SEAL - RH OUTER New	1	\$	151.00	+
13	FRONT DOOR COVER - RH Cut	1	\$	270.00	✓
14	WING MIRROR MOUNTING - RH New	1	\$	1,130.00	x
15	WING MIRROR CAP - RH Repair	1	\$	203.00	x
SUB TOTAL SPARE PARTS		:	\$	5,894.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SDY 886 G - REAR

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	REAR DOOR - RH <i>Distorted</i>	1	\$	2,962.00	✓
2	REAR DOOR OUTER SEAL - RH <i>new</i>	1	\$	151.00	✓
3	BONDING AGENT ?	1	\$	51.00	?
4	CLEANING SOLUTION ?	1	\$	74.00	?
5	APPLICATOR ?	1	\$	8.00	?
6	REAR DOOR CATCH - RH ? <i>BT</i>	1	\$	134.00	?
7	REAR DOOR HANDLE - RH <i>new</i>	1	\$	398.00	+
8	REAR DOOR WINDOW APERTURE SEAL - RH OUTER <i>MP</i>	1	\$	151.00	✓
9	REAR DOOR COVER - RH <i>cut</i>	1	\$	238.00	✓
10	REAR WHEEL ARCH COVER - RH <i>cut</i>	1	\$	180.00	✓
11	DUNLOP TYRE <i>new</i>	S/N		TBC	+
12	SUNDRRIES ?		\$	400.00	?
TOTAL SPARE PARTS (FRONT & REAR)			:	\$ 10,641.00	
TOTAL LABOUR CHARGES			:	\$ 6,612.00	
GRAND TOTAL			:	\$ 17,253.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.