

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chee So Chow

Date: 29 Apr 2022

Preliminary Advice

Vehicle No	: GBK1245Y	Accident Date	: 09/04/2022
Make	: RENAULT KANGOO	Policy No.	: DMCVSNW00150822101
Assignment Date	: 27/04/2022	Excess	: S\$450.00
Date of Inspection	: 28/04/2022	Est. Duration of Repair	: 16
Inspection At	: AUTO INSURE PTE LTD (HQ) (WOODLANDS) 6 MARSILING LANE SINGAPORE 739145		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	32,615.20
Revised Amount	:S\$	21,800.20
Check Items (Estimated)	:S\$	9,258.00
Total	:S\$	31,058.20

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 67,000.00
COE / PARF Rebate	:S\$ 18,147.00

Salvage Value	:S\$
Margin for Repair	:S\$ 48,853.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.